CITY OF BLOOMINGTON

PHASE I HISTORIC SURVEY

DIMMETT'S GROVE NEIGHBORHOOD

VOLUME 4 OF 4

CONTENTS:

SECTION	STREET
11	Prairie - Olive to Jackson
12	Gridley - Jefferson to Oakland
13	McLean - Jefferson to Oakland
14	Evans - Jefferson to Oakland
15	Clayton - Jefferson to Oakland
16	Clinton - Jefferson to Oakland
17	Robinson - Washington to Oakland

PREPARED BY

WILLIAM E. GIVENS, ASSOCIATE PLANNER
MCLEAN COUNTY REGIONAL PLANNING COMMISSION

PREPARED FOR

THE CITY OF BLOOMINGTON

HISTORIC PRESERVATION COMMISSION

SEPTEMBER 1, 1990



Illinois Historic Preservation Agency

This publication was financed in part with federal funds provided by the U.S. Department of the Interior and administered by the Illinois Historic Preservation Agency. However, the contents and opinions do not necessarily reflect the views or policies of the U.S. Department of the Interior or the Illinois Historic Preservation Agency. The Illinois Historic Preservation Agency is an equal opportunity employer.

Address:	302 S. PRAIRIE BLOOMINGTON, IL.
Present Owner:	DAVID LEWIS
Parcel Number:	21-04-452-004
Historical Name:	
Construction Date:	CIRCA 1890
Photo:	Roll No. 12 Frame No. 17
Architect/ Builder:	
Materials:	WOOD FRAME & TRIM, ASEFSTOS SIDING, BRICK FOUNDATION & CHIMNEY
Overall shape or p	lan, number of stories and roof shape: /RREGULAR SHAPED 25TORY SLE, CENTRAL HIP WITH DOMINANT FRONT GABLE, LOWER CROSS GABLE 98:
-	efinition on reverse)
oone v	Excellent; Good; Deteriorated
Describe major phy	sical changes from original construction: <u>SDWG ATPLIED</u> , CONVERTED
Potential National a. Individually b. As a part of a	(yes/no)
c. Explain ractor	mic for possingua acong
	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) historical associations.
Surveyor:	WILLIAM GIVENS

Address:	304 S. PRAIRIE BLOOMINGTON, IL.
Present Owner:	HENRYNUTT
Parcel Number:	21-04-453-001
Historical Name:	
Construction Date:	CRCA 1873
Photo:	Roll No. <u>/2</u> Frame No. <u>/8</u>
Architect/ Builder:	
Materials:	WOD FRAME CLAPBOARDS FIRM, BRICK FOUNDATION, RBB PAYWOOD SIDING ON LOWER LEVEL, FRONT
verall shape or pl	an, number of stories and roof shape: 2/2 STORY GABLE FRONT
Subsidiary Building	s:
Condition: (See de	finition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	FLYWOOD SIDING APPLIED TO FRANT
Potential National	Register:
a. Individuallyb. As a part of ac. Explain rations	district (yes/no) (ye
Comments: Is the b	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s)
,	
Surveyor: W/	1/2 IAM GILLENS

Address: .	306 S. PRATRIE BLOOMINGTON.IL
Present Owner:	JUAN MADRIGAL
Parcel Number:	21-04-453-002
Historical Name:	
Construction Date:	CIRCA 1873
Photo:	Roll No. 12 Frame No. 19
Architect/ Builder:	
Materials:	NOOD FRAMERSOME TRIM, ASPHALT COMPOSITION SIDING, PARGETED FOUNDAT
	an, number of stories and roof shape: 2 STORY GABLE FRONT FAMILY
WITH LOWEK Subsidiary Building	ENCLOSED FULL WITH PORCH, GAMBREL ROOFED ADDITION OVER PORCES
_	finition on reverse)
COMMICTOR: (See de	Excellent; Good; Deteriorated
	ical changes from original construction: FRONT PORCH ENCLOSED, SIDING
APPLIED.	CHMBREL ROOFED ADDITION OVER PORCH PRESENTLY
IN PROG	
Potential National	Register:
a. Individuallyb. As a part of ac. Explain rational	(yes/no) // (yes/no)
<u> </u>	
	uilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) istorical associations.
)	
Surveyor: Wi	9-21-90

Address:	308 S. PRAIRIE
	BLOOMINGTON, IL.
Present Owner:	JON THETARD
Parcel Number:	21-04-453-003
Historical Name:	
Construction Date:	CIRCA 1890
Photo:	Roll No. 12 Frame No. 20
Architect/ Suilder:	
Materials:	WOOD FRAME LAPBOARDS & TRIM. BRICK FOUNDATION & PIERS.
_ 1/CTORIA	an, number of stories and roof shape: 2 /2 STORY CROSS GABLE. WITH FULL WIDTH POXCH & TOMINANT SIDE GABLE.
Subsidiary Building	
Condition; (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction:
D	Pagi stor!
Potential National a. Individually	(yes/no)
b Acapart of a	ale for potential designation - specify criteria A, B, C, D, or combination of any.
	<u> </u>
Comments: Is the land/or h	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) nistorical associations.
)	
Surveyor:	9-21-9E

Address:	310 S. PRARIE BLOOMINGTON, IL
Present Owner:	STEFANHIRSCH
Parcel Number:	21-04-453-004
Historical Name:	
Construction Date:	CIRCA 1890
Photo:	Roll No. 12 Frame No. 21
Architect/ Builder:	
Materials:	WOOD FRAME, CLAPBOARDS ETTRIM. BRICK FOUNDATION
verall shape or pl PLAN MITT Subsidiary Building	an, number of stories and roof shape: \[\sum_STORY \ IRREGULAR \tau-SHAPEL \\ \frac{A}{A} \sum_SERIES \text{OF} ADDITIONS WITH PARALLEL & CROSS SABLED \\ \text{cs:} \[ROOFS DEPENDING ON DIRECTION OF VIEW. \]
Condition: (See de	efinition on reverse)
•	Excellent; Good; Deteriorated
Describe major phys	Sical changes from original construction: #OSE PROBABLY STARTED AS
Potential National	Register:
a. Individually	(yes/no)
Comments: Is the band/or h	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) istorical associations.
Surveyor:	7-21-40 7-21-40

DEFINITIONS FOR CONDITION:

EXCELLENT - All original architectural details are apparently intact and major elements (foundations, walls, windows and roof) are in repair.

GOOD - Almost all of the elements characterizing "EXCELLENT" but missing some original details and requiring some work but not stabilization.

DETERIORATED - All or some major elements (foundations, walls, windows and roof) require replacement. Original architectural details may or may not still be present.

CRITERIA FOR EVALUATION OF NATIONAL REGISTER POTENTIAL:

The quality of significance in American history, architecture, archeology, engineering and culture is present in districts, sites, buildings, structures and objects that possess integrity of location, setting, design, materials, workmanship, feeling and association:

- A. that are associated with events that have made a significant contribution to the broad patterns of our history; or
- B. that are associated with the lives of persons significant in our past; or
- C. that embody the distinctive characteristics of a type, period or method of construction, or that represent the work of a master, or that possess high artistic values, or that represent a significant and distinguishable entity whose components may lack individual distinction; or
- D. that have yielded, or may be likely to yield, information important in prehistory or history.

•		
Address:	104 S. GRIDLE YST BLOOMINGTON, IL.	
Present Owner:	JANISSWANTON	
 Parcel Number:	21-04-415-002	
Historical Name:	<u> </u>	
Construction Date:	CIRCA 1870-1895	
Photo:	Roll No. // Frame No. //2	
Architect/ Builder:	<u>.</u>	
Materials:	FOUNDATION & CHIMNE	
verall shape or pl	lan, number of stories and roof shape:/	1/2 STORY GABLE FROMT
FAMILY 1	WITH FULL WIDTH 1370R	DY PORCH
Subsidiary Building	gs:	
Condition: (See de	efinition on reverse)	
	Excellent; $Good$ /;	Deteriorated
Describe major phys	sical changes from original construction:	FRONT PORCH ALTERED,
SIDINO	AFRIED	
Potential National	Register:	
a. Individuallyb. As a part of a	district	(yes/no)((yes/no)
c. Explain ration	ale for potential designation - specify cri	teria A, B, C, D, or combination of any.
Comments: Is the land/or h	building common, special or unique (one-of- vistorical associations.	a-kind) in any regard and specify feature(s)
)		
Surveyor: W	ILLIAM GIVENS	

Address:	208 S. GRIDLEY ST. BLOOMINGTON, IL.		
Present Owner:	BILL FITZGERALD		
Parcel Number:	21-04-418-010		,
Historical Name:			entended while the
Construction Date:	CIRCA 1885		
Photo:	Roll No. // Frame No. /3		
Architect/ Builder:			
Materials:	NOOD FRAME, SIDING	TY, PARSETED FOUNDA	TIM _
Subsidiary Building	lan, number of stories and roof shape: & **MUNITH DOMINANT FRO gs: effinition on reverse) Excellent; Good;		BLED_
Describe major phys	sical changes from original construction:		
	<u> </u>		
Potential National	Rogistar'		
a. Individually	district ale for potential designation - specify cri	(yes/no) // (yes/n	
	building common, special or unique (one-of- nistorical associations.	a-kind) in any regard and specify feature	

Address:	DIO S. GRIDLEY ST.
	BLOOMINGTON, IL
Present Owner:	STEVE DUBOSH
Parcel Number:	21-04-418-003
Historical Name:	
Construction Date:	CIRCA 1885
Photo:	Roll No Frame No
Architect/ Builder:	
Materials:	NOOD FRAME & TRING, ALUMINUM SIDING, BRICK FOUNDATION & CHINNEY
<u> VICTORIA</u>	lan, number of stories and roof shape: 2/2 570KV CROSS GABLED
Subsidiary Building	
Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction: <u>SIDING APPLIED</u> , BALUSTRAI
MISSING_	FROM FRONT PORCH
Potential National	Register:
a. Individually	(yes/no)
b. As a part of a	district (yes/no)ale for potential designation - specify criteria A, B, C, D, or combination of any.
-	
	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) distorical associations.
 ·	1
Surveyor:	11LIAM 61UENS

)	¢302/2	
Address:	302 S. GRIDLEY ST. BLOOMINGTON, IL.	
Present Owner:	HERBERT HANNER	
Parcel Number:	21-04-456-001	
Historical Name:		411
Construction Date:	<u>CIRCA 1910</u>	
Photo:	Roll No Frame No	
Architect/ Builder:		
Materials:	WOOD FRAME, CLAPSOARDS & TRIM. BRICK FOUNDATION	
Verall shape or pl	an, number of stories and roof shape: <u>RECTANGUAR SHAPE</u>	> (
Subsidiary Building		
Condition: (See de	finition on reverse)	•
	Excellent; Good; Deteriorated	
Describe major phys	ical changes from original construction:	
	<u>- </u>	
Potential National	Register:	
a. Individually	(yes/no)	
·	CÉD	
Comments: Is the b	wilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) istorical associations.)
)		
Surveyor:Date:	WILLIAM GIVENS	

Address:	304 S. GRIDLEY ST.	
	BLOOMINGTON, IL.	
Present Owner:	HERBERTHANNER	
Parcel Number:	21-04-456-001	
Historical Name:		
Construction Date:	CIRCA 1870	
Photo:	Roll No//_ Frame No/6	
Architect/ Builder:	· · · · · · · · · · · · · · · · · · ·	
Materials:	WOOD FRAME & TRIM, SOME SIDIMO, FLYWOOD	SIPING, PARGETED FOUNDATION
WNG L Subsidiary Buildin	-SAAPED ngs:	
Condition: (See C	definition on reverse) Excellent; Good;	Deteriorated
Describe major phy		WINDOWS CHANGED,
Potential National	Register:	· · · · · · · · · · · · · · · · · · ·
a. Individually		(yes/no) (yes/no) teria A, B, C, D, or combination of any.
Comments: Is the and/or	building common, special or unique (one-of-a historical associations.	a-kind) in any regard and specify feature(s)
)	•	
Surveyor:	WILLIAM SIDENS	

Address:	305 S. GRIDLEY ST. BLOOMINGTON, IL.	
Present Owner:	MARGUENTE CLOSE	
Parcel Number:	21-04-452-005	
Historical Name:		
Construction Date:	CIRCA 1867	
Photo:	Roll No. // Frame No. 20	
Architect/ Builder:		
Materials:	WOOD FRAME, CLAPBOARDS & TRIM, BRICK FOUNDATION	
verall shape or p	Lan, number of stories and roof shape: _/STORY, L-SHAPED, SIDE HOUSE WITH FHAT ROOFED REAR WING	
Subsidiary Buildin	<u></u>	
Condition: (See d	efinition on reverse)	
	Excellent; Good; Deteriorated	
Describe major phy	sical changes from original construction:	_
Potential National	Pagietar'	
T 11 11 11	(yes/no) (/2)	
h. As a part of a	district (yes/mo) VES	_
c. Explain ration	ale for potential designation - specify criteria A, B, C, D, or combination of any.	
<u></u>	$C \notin D$	
	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) istorical associations.	
<i>'</i> .		
Surveyor:	116/AM GIVENS 9-24-98	

Address:	305/SA3BS, GRIDLEY BLOOMINGTON, IL.
Present Owner:	RICHARD HUNDMAN
Parcel Number:	21-04-453-005
Historical Name:	
Construction Date:	<u>CIRCA</u> 1867
Photo:	Roll No. $//$ Frame No. $2/$
Architect/ Builder:	
Materials:	WOOD FRAME, SHUTTERS ÉCOLUMNS, ARTIFICIAL SIDING, BEYCK FOUNDATION
Verall shape or pi	lan, number of stories and roof shape: 2 STORY GABLE FRONT
FAMILY WI	TH LOWER ISTORY FULL WIDTH FORCH
Subsidiary Building	
Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction: <u>SIDING APPLED</u> , APPEARS
THAT SON	LE WINDOWS HAVE BEEN COVERED IN THE SIDING
AFTLICAT	70N
Potential National	Register:
a. Individually	(yes/no) //o
b. As a part of ac. Explain ration	ale for potential designation - specify criteria A, B, C, D, or combination of any.
Comments: Is the and/or	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) historical associations.
) .	
Surveyor:	WILLIAM OUDENS

Address:	306 S. GRIDLEY ST. BLOOMINGTON, IL.	
Present Owner:	RICK ROOTS	
Parcel Number:	21-04-456-008	
Historical Name:		
Construction Date:	<u>CIRCA 1870-80</u>	
Photo:	Roll No/_ Frame No/7	
Architect/ Builder:		
Materials:	MODERAME & TRIM, ASERSTOS SUDING BENY FOUNDATION, CONCRETE	
	ASBESTOS SIDING, BEKK FOUNDATION, CONCRETE PORCH & STEPS, METAL BALLISTRATE & AUNING SUPPORTS	_
verall shape or pl	an, number of stories and roof shape: 1/2 STORY GABLE FRONT-	_
	FAMILY	
Subsidiary Building	s:	
Condition: (See de	finition on reverse)	
	Excellent; Good; Deteriorated	
Describe major phys	ical changes from original construction: <u>SIDING APPLIED</u> , FRONT	
Potential National	Register:	
T., 12., 2.1., 11.,	(yes/no) NO	
b. As a part of a		_
c. Explain rationa	te for potential designation. Specify effected in, b, c, 2, ci vimini.	
	uilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) istorical associations.	
)		
	in that entrals	
Surveyor: W	14/AM 61VENS	
	\cdot	

Address:	306/2 S. GRIDLEY BLOOMINGTON, IL.
Present Owner:	BARBARASCHNETDER
Parcel Number:	21-04-456-009
Historical Name:	
Construction Date:	CIRCA 1905
Photo:	Roll No. $\frac{18}{100}$ Frame No. $\frac{18}{100}$
Architect/ Builder:	
Materials:	WOOD FLAME, CLAPBOARDS & TRIM, BRICK FOUNDATION & CHIMNEY
CRAFTSMAN Subsidiary Building Condition: (See de	Lan, number of stories and roof shape:
Potential National a. Individually b. As a part of a c. Explain ration	district (yes/no) <u>VES</u> ale for potential designation - specify criteria A, B, C, D, or combination of any.
Comments: Is the and/or I	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) distorical associations.
Surveyor: //	9-25-90

•			•
Address:	307 S. GRIDLEVST. BLOOMINGTON, IL.		
Present Owner:	RUSSELL FRANCOIS		
Parcel Number:	21-04-453-006		
Historical Name:	TIPTON HOUSE		
Construction Date:	CIRCA 1860		
Photo:	Roll No Frame No		
Architect/ Builder:		·	
Materials:	WOOD FRAME, CLAPBON	ARDS PATION	
Overall shape or pl 2 STORY 17 Subsidiary Building	an, number of stories and roof shape: ALIANATE WITH /STORY, Land	SQUARE SHAPED, HIPPE SHAPED REAR ADDITION	D ROOK,
Condition: (See de	finition on reverse)		
	Excellent; Good	_; Deteriorated	
Describe major phys	sical changes from original construction	: NING REMOVED FROM	W NORTH
AND OUT	- DURING 1978 É 7		
Potential National	Register:	٠,	
a. Individually	N. Justine	(yes/no)	<i>i</i> a .
b. As a part of a c. Explain rationa	ale for potential designation - specify		of any.
	ouilding common, special or unique (one- istorical associations.	of-a-kind) in any regard and specify	feature(s)
)		,	
Surveyor: //	1/LLIAM 61VENS		

,				
Address:	3085. GRIDLEY ST. BLOOMINGTON, IL.			
Present Owner:	JAMES ROBERTS			
Parcel Number:	21-04-456-010			
Historical Name:				
Construction Date:	CIRCA 1870			
Photo:	Roll No Frame No			
Architect/ Builder:	·			
Materials:	WOOD FRAME & SOME TRIM, ALIMINUM SIDING	15 BRICK É	BLOCK FEUNDAT	TON_
	Lan, number of stories and roof shape:			
Subsidiary Building	gs:			
Condition: (See de	efinition on reverse)	/		
	Excellent; Good	Deteriorated _	•	
Describe major phys	sical changes from original construction: **PORCH FNCLOSED FOR ROCE *** PORCH FNCLOSE	SIDING APP DM, DRIVE-UN	LIED, SMALL A DEL GARAGE	<u>DDTO</u> P
Potential National	Register:		,	,
a. Individuallyb. As a part of ac. Explain ration	district ale for potential designation - specify cr	(ye	s/no) s/no) r combination of any.	
<u> </u>				
Comments: Is the and/or 1	building common, special or unique (one-of nistorical associations.	-a-kind) in any rega	rd and specify feature(s)	
Surveyor:	VILLAM GIVENS			

Address:	313/2 S. GRIDLEY
	BLOOMINGTON, IL.
Present Owner:	HARRYSCHRAMM
Parcel Number:	21-04-453-008
Historical Name:	
Construction Date:	CIRCA 1900-1920
Photo:	Roll No. $//$ Frame No. 23
Architect/ Builder:	
Materials:	WOOD FRAME & TRIM, ASBESTOS SIDING, BRICK FOUNDATION
verall shape or pl	Lan, number of stories and roof shape: 2/2 STORY, HIPPED ROOF
Subsidiary Building	35:
-	efinition on reverse)
Condition: (See de	Excellent; Good; Deteriorated
•	
<u>^</u>	sical changes from original construction: SIDING APPLIED, FROMT
PORCH EX	ICLOSED
Potential National	(yes/no) (yes/no)
a. Individuallyb. As a part of ac. Explain ration	- 1/m
	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) ustorical associations.
Surveyor:	WIAM GIVENS

Address:	404 S. GRIDLEY BLOOMINGTON, IL.	
Present Owner:	SARAH MANDEL	
Parcel Number:	21-04-458-001	A T
Historical Name:		
Construction Date:	CIRCA 1900-1920	
Photo:	Roll No Frame No	
Architect/ Builder:		
Materials:	WOOD FRONT, PLYWOOD POORS E. LOWER FRONT, ASPHALT COMPOSITION SHINGLE ON FRONT PARAPET, REMAINING WALLS CONCRETE BLOCK	•
worall shape or pl	olan, number of stories and roof shape: /STARY, FLAT ROOFED	
SARAGE TY	YPE STRUCTURE WITH PARATETS	
Subsidiary Building	مسيع <i>ا</i> بر جراء	
Condition: (See de	definition on reverse)	
	Excellent; Good; Deteriorated	
Describe major phys	ysical changes from original construction: FRONT WALL COVERED	>
WITH ASPA	ALT SHINGLES & PLYWOOD	
Potential National		
a. Individuallyb. As a part of a	(yes/no) (yes/no) (yes/no)	
c. Explain ration	nale for potential designation - specify criteria A, B, C, D, or combination of any.	
· · ·		
Comments: Is the and/or	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) historical associations.	
)		
Surveyor:	VILLIAM GIVENS	

Address:	406 S. GRIDLEY BLOOMINGTON, IL.		. ——
Present Owner:	TERRENCE DOLAN		
Parcel Number:	21-04-458-006		
Historical Name:			
Construction Date:	CIRCA 1900		######################################
Photo:	Roll No// Frame No25_		g ar ang tang karalang di dianggan kan di marang
Architect/ Builder:			
Materials:	WOOD FRAME, TRIM & SOME CLAPBOARDO, AST BRICK FOUNDATION	PHALT COMPOSITION SIDING	ź,
MASSED 1/	AN WITH OFF-CENTER	FINCIDSED FRONT PORCH	FRONT
Subsidiary Building	gs:		
Condition: (See de	finition on reverse)		
	Excellent; Good __	<u> </u>	
Describe major phys	sical changes from original construction	on: PORCH ENCLOSED	
Potential National a. Individually	Register:	(yes/no)	
b. As a part of a	district le for potential designation – specif	(yes/no) (ye	
	ouilding common, special or unique (on istorical associations.	e-of-a-kind) in any regard and specify featur	e(s)
)			
Surveyor: k//	11/AM GIVENS 9-25-90		

Address:	502 S. GRIDLEY BLOOM INGTON, IL.
Present Owner:	ALAN SPEAR
Parcel Number:	21.04-460.001
Historical Name:	
Construction Date:	CIRCA 1895
Photo:	Roll No. $//$ Frame No. $/$ 26
Architect/ Builder:	
Materials:	WOOD FRAME & TRIM, ARTIFICIAL SIDING, ROCK FACED CONCRETE BLOCK
verall shape or pi	lan, number of stories and roof shape: T-SHAPED //2 STORY
Subsidiary Building	
Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
	sical changes from original construction: COVER ALL SIDING JOB,
Potential National	Register:
a. Individuallyb. As a part of ac. Explain ration	district (yes/no) (yes/no) (yes/no) (yes/no) (yes/no)
· · · · · · · · · · · · · · · · · · ·	
Comments: Is the and/or 1	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) historical associations.
)	
Surveyor:	WILLIAM GIVENS

Address:	504 S. GRIDLEY BLOOMINGTON, IL.
Present Owner:	ALAN SPEAR
Parcel Number:	21-04-460-002
Historical Name:	
Construction Date:	<u>CIRCA 1895</u>
Photo:	Roll No/_ Frame No27
Architect/ Builder:	
•	
Materials:	MOOD FRAME & TRIM. ARTIFICIAL SIDING, BRICK FOONDATION & CHIMNEY
Subsidiary Building Condition: (See de	Excellent; Good; Deteriorated Sical changes from original construction:SIDING APPLIED FRONT
Potential National	Register:
a. Individuallyb. As a part of ac. Explain rational	district (yes/no) // // // // // // (yes/no) // // // // // // // // // // // // //
	uilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) istorical associations.
)	
Surveyor:// Date:	1/1LIAM GUENS 9-25-90

		·
Address:	506 S. GRIDLEY BLOOMINGTON, IL	·
Present Owner:	EVA BALL	
Parcel Number:	21-04-460-003	
Historical Name:		
Construction Date:	CIRCA 1895	
Photo:	Roll No Frame No	
Architect/ Builder:	<u>. </u>	
Materials:	WOOD FRAME & TRIM, ASPHALT COMPOSITION	SIDING, BRICK FOUNDATION
		-1/2 STORY GABLE FRANT
Subsidiary Building	s:	
Condition: (See de	finition on reverse)	
	Excellent; Good _	, Deteriorated
Describe major phys	ical changes from original constructi	on: SIDING APPLIED, PORCH
ENCLOSE	>	
	D	•
Potential National a. Individually b. As a part of a	district	(yes/no) <u>//</u> (yes/no)
c. Explain rationa	ale for potential designation - specif	y criteria A, B, C, D, or combination of any.
	ouilding common, special or unique (or istorical associations.	e-of-a-kind) in any regard and specify feature(s)
)		
Surveyor:	WILLIAM ONEAS	

Address:	BLOOMINGTON, IL.
Present Owner:	RALPH ZABEL
Parcel Number:	21-04-462-001
Historical Name:	MICHAEL C. FITZGERALD
Construction Date:	<u>Circa</u> 1970
Photo:	Roll No. // Frame No. 29
Architect/ Builder:	
Materials:	NOOD FRAME, TRIM & SIDING. CONCRETE FOUNDATION.
erall shape or pl GABLE FRO Subsidiary Building	an, number of stories and roof shape: <u>LONG RECTANOUNAR SHAPED</u> WT, ISTORY COMMERCIAL OFFICE BUILDING s:
Condition: (See de	finition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	ical changes from original construction:
Potential National	Register:
a. Individually	(yes/no)
b. As a part of ac. Explain rational	le for potential designation - specify criteria A, B, C, D, or combination of any.
Comments: Is the band/or h	wilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) istorical associations.
Surveyor:Date:	WILLIAM GIVENS

Address:	606 S. GRIDLEY BLOOMINGTON, IL.
Present Owner:	LOUIS STARCEVIC
Parcel Number:	21-04-462-008
Historical Name:	
Construction Date:	_CIRCA 1900
Photo:	Roll No/_ Frame No
Architect/ Builder:	
Materials:	WOOD FRAME & TRIM, ARTIFICIAL SIDING, BRICK CHIMNEY, BLOCK FOUNDATION
verall shape or pl FAMILY W Subsidiary Building	an, number of stories and roof shape: _//2 5 TORY GABLE FRONT TH FLAT ROOFED, ENCLOSED FULL WIDTH PORCH s:
-	finition on reverse)
CONTRICTOR: (Dec de	Excellent; Good; Deteriorated
Density major physic	ical changes from original construction:
Describe major phys	Ical Changes from Original Construction.
Potential National	· /-
a. Individuallyb. As a part of a	(yes/no)
b. As a part of a c. Explain rationa	ale for potential designation - specify criteria A, B, C, D, or combination of any.
	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) istorical associations.
)	
Surveyor: ///	141AM GIVENS 9-25-90

Address:	608 S. GRIDLEY BLOOMINGTON, IL.
Present Owner:	PATRICIA WILKINSON
Parcel Number:	21-04-462-009
Historical Name:	
Construction Date:	<u>C/RCA 1900</u>
Photo:	Roll No Frame No
Architect/ Builder:	
Materials:	WOOD FRAME & TRIM, STEEL SIDING BLOCK FOUNDATION, BRICK CHIMILEY, CONCRETE FORCH STOOP an, number of stories and roof shape: 1/2 STORY GABLE FRONT
FAMILY	,
Condition: (See de	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction:
Potential National	,
a. Individuallyb. As a part of ac. Explain ration	ale for potential designation - specify criteria A, B, C, D, or combination of any.
Comments: Is the l	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) distorical associations.
)	
Surveyor:	WILLIAM SIVENS 9-25-90

DEFINITIONS FOR CONDITION:

EXCELLENT - All original architectural details are apparently intact and major elements (foundations, walls, windows and roof) are in repair.

GOOD - Almost all of the elements characterizing "EXCELLENT" but missing some original details and requiring some work but not stabilization.

DETERIORATED - All or some major elements (foundations, walls, windows and roof) require replacement. Original architectural details may or may not still be present.

CRITERIA FOR EVALUATION OF NATIONAL REGISTER POTENTIAL:

The quality of significance in American history, architecture, archeology, engineering and culture is present in districts, sites, buildings, structures and objects that possess integrity of location, setting, design, materials, workmanship, feeling and association:

- A. that are associated with events that have made a significant contribution to the broad patterns of our history; or
- B. that are associated with the lives of persons significant in our past; or
- C. that embody the distinctive characteristics of a type, period or method of construction, or that represent the work of a master, or that possess high artistic values, or that represent a significant and distinguishable entity whose components may lack individual distinction; or
- D. that have yielded, or may be likely to yield, information important in prehistory or history.

Address:	IDIS MCLEAN ST.		
Address.	BLOOMINGTON, IL.		
Present Owner:	THERESA HAFFNER		
Parcel Number:	21-04-415-007		
Historical Name:			
Construction Date:	CIRCA 1880-95		
Photo:	Roll No. // Frame No. 32		
Architect/ Builder:			
Materials:	NOW FRAME & TRIM, ARTIFICIAL SIDING,	BRICK FOUNDATION	
overall shape or pi	lan, number of stories and roof shape:	IRREGULAR SHAPE	D, 2½
Subsidiary Building	gs:GARAGE		
	efinition on reverse)		
	Excellent; Good	; Deteriorated	
Describe major phy	sical changes from original construction	on: COVER-ALL SID,	ING JOB
APPLIED		•	
Potential National	Register:		
a. Individually		(yes/no) <i>MC</i> (yes/no) <i>MC</i>	2
b. As a part of ac. Explain ration	district ale for potential designation - specif	y criteria A, B, C, D, or combination	of any.
		·	
Comments: Is the and/or	building common, special or unique (on historical associations.	e-of-a-kind) in any regard and specif	y feature(s)
Surveyor:	WILLIAM GIVENS 9-25-90		

Address:	103 5. MCLEAN ST. BLOOM/NGTON, /L.	
Present Owner:		
Parcel Number:	21-04-415-008	
Historical Name:		
Construction Date:	CIRCA 1890	
Photo:	Roll No. // Frame No. 33	
Architect/ Builder:	· .	
Materials:	WOOD FRAME, SIDING ÉTRIM, BRICK, FOUNDA	TINKE PLES.
	4/N/19, 12/14/11	700 4
verall shape or pl	an, number of stories and roof shape:	1/2 STORY, L-SHAPED
TUDOR 1	VELUENCED VICTORIAN	<u> </u>
Subsidiary Building	s:	
Condition: (See de	finition on reverse)	
	Excellent; Good;	Deteriorated
Describe major phys	ical changes from original construction:	
		
Potential National	Register:	
a. Individually		(yes/no) // (yes/no) // s eria A, B, C, D, or combination of any.
	CÉD	
	uilding common, special or unique (one-of-a istorical associations.	-kind) in any regard and specify feature(s)
)		
Surveyor:	WILLIAM GIVENS	

,	
Address:	BLOOMINGTON, IL.
Present Owner:	KENT WHITESIDE
Parcel Number:	21-04-416-007
Historical Name:	
Construction Date:	CIRCA 1905-1920
Photo:	Roll No/ Frame No. 34
Architect/ Builder:	
Materials:	WADD FRAME FIRM, STUCCO WALLS, BRICK CHIMNEY
Verall shape or pl WITH CENTA Subsidiary Building	an, number of stories and roof shape: //z STORY, SUPE GABUED HOUSE FRED SHED DORMER & FULL WIDTH FRONT PORCH SS: STORAGE SHED
Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction: ROUNDATION PARGETED
Potential National	Register:
a. Individually	(yes/no)
	<u> </u>
	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) distorical associations.
Surveyor:	WICLIAM GIVENS

Address:	204 S. MCLEAN ST.
	BLOOMINGTON, IL
Present Owner:	JON THETARD
Parcel Number:	21-04-419-006
Historical Name:	
Construction Date:	CIRCA 1895
Photo:	Roll No/_ Frame No35
Architect/ Builder:	
Materials:	WOOD FRAME, SOME TRIM,
	BRICK FOUNDATION, ALUMINUM SIDING, CONCRETE
ì	FORCH & FRONT STEED
verall shape or pl	an, number of stories and roof shape: <u>RECTANGULAR SHAPED</u> 2
	WITH CROSS GABLES, DAMINANT FRONT GABLE
Subsidi a ry Building	
Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
	sical changes from original construction: <u>ONER-ALL SIDING JOB</u> ,
FRONT PO	CCH REPLACED & OVERHANG ALTERED
:	
Potential National	· · · · · · · · · · · · · · · · · · ·
a. Individuallyb. As a part of a	(yes/no) (yes/no) (yes/no)
b. As a part of a c. Explain rationa	ale for potential designation - specify criteria A, B, C, D, or combination of any.
, , , , , , , , , , , , , , , , , , , 	
	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) distorical associations.
)	
Surveyor: <i>U</i>	11/41AM GIVENE 9-26-90
- · · · · · · · · · · · · · · · · · · ·	, , , , , , , , , , , , , , , , , , , ,

Address:	DOB S. MCLEAN ST. BLOOMINGTON, IL			
Present Owner:	EARL CAMPBELL		A COM	
Parcel Number:	21-04-419-007			
Historical Name:				
Construction Date:	CIRCA 1900-1920			A
Photo:	Roll No Frame No		100 (100 (100 (100 (100 (100 (100 (100	
Architect/ Builder:				
Materials:	WOOD FRAME CLAPE	OARPS VUNDATION É	CHIMNEY	
4. S&U	V/2 6/-	2 5TOR	Y HIPPET	> 130F
Subsidiary Building	efinition on reverse)			
CORRECTION. (See at	Excellent; Good	; Deteriorated	d .	
Describe major phys	sical changes from original constructi	on: FRONT	PORCH & ST	TEPS
Potential National	Pogistor:			
a. Individually b. As a part of a		((yes/no) // (yes/no)	any.
and/or h	PISTRICT IF FRONT & OTHER MAINTENA	DRE CONTRI	いしてべん 1	NA
Surveyor:Date:	NULLIAM GIVENS 9-26-90		LANGEN SER	KHOKMEL,

Address:	207-207/2 S. MCLEAN BLOOMINGTON, IL.	11	il e. 🕶
Present Owner:	EARL EWALD		The state of the s
Parcel Number:	21-04-418-007		É
Historical Name:			
Construction Date:	CIRCA 1910		
Photo:	Roll No Frame No37		
Architect/ Builder:			4.
Materials:	WOOD FRAME, CLAPBON & TRIM, BRICK FOUND	DATIONE CHIMNE	
Tagoria	METAL RIDGE TRIM plan, number of stories and roof shape: RE WITH CENTERED FRO	2/2 STORY	HIPPED ROOF WIDTH PORCH
Subsidiary Buildin			
Condition: (See	definition on reverse)		
4	Excellent; Good		•
Describe major ph	ysical changes from original construction	on:	
Potential Nationa	l Register:	•	,
a. Individually	I Neglocal	(yes/no)	10
	a district onale for potential designation - specif	(yes/no) v criteria A, B, C, D, or comb	pination of any.
c. Explain ratio	onate for potential designation of EC	>	
Comments: Is the	e building common, special or unique (on historical associations.	e-of-a-kind) in any regard and	d specify feature(s)
,			
Surveyor:	WILLIAM GIVENS		

Address:	208 MCLEAN ST.
	BLOOMINGTON, IL.
Present Owner:	THELMA RYDER
Parcel Number:	21-04-419-008
Historical Name:	
Construction Date:	_CIRCA 1910
Photo:	Roll No. $/2$ Frame No. $/$
Architect/ Builder:	
Materials:	WOOD FRAME, CLAPBOARDS \$TRIM, BRICK FOUNDATION PIETS & CHIMNEY,
	SLATE ROOF WITH METAL RIDGE TRIM
verall shape or p	lan, number of stories and roof shape:
Subsidiary Building	An, number of stories and roof shape: <u>L-SHAPED</u> , 2578RY, OF CENTRAL BLOCK WITH GABLED WING ON FRONT CORNER GS: FORMING L'I NITH LOWER FULL WIDTH FORCH
Condition: (See de	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction:
Potential National	Register:
a. Individually	(yes/no) NO
b. As a part of a	district (yes/no) //ES ale for potential designation - specify criteria A, B, C, D, or combination of any.
c. Explain ration	$C \not\in D$
	building common, special or unique (one-of-a-kind) in any regard and specify feature(s)
)	
,	u la mande
Surveyor: ///	GLIM GIVEND

)		•	
Address:	209-2091/2 211-211/2 S. MCLEAN BLOOMINGTON, IL.		
Present Owner:	ROBERTMONTGOMERY		
Parcel Number:	21-04-418-008		
Historical Name:	LAWRENCE FUNK		
Construction Date:	CIRCA 1910		
Photo: .	Roll No. 12 Frame No. 2		
Architect/ Builder:	A. PILSBURY		
Materials:	WOOD FRAME, CLAPBOARD ÉTRIM, BRICK FOUNDA	•	
overall shape or particle of the control of the con	plan, number of stories and roof shape:	YR STORY, HIPPE OTH FORCH	ED ROOF NITH
	definition on reverse)		
	Excellent; Good;	Deteriorated	
Describe major phy	ysical changes from original construction:		
		<u>:</u>	
Potential Nationa a. Individually	l Register:	(yes/no)	10
h. As a part of	a district nale for potential designation – specify crit	(yes/no) teria A, B, C, D, or combinat	ion of any.
		·	
Comments: Is the and/or	building common, special or unique (one-of-a	a-kind) in any regard and spe	cify feature(s)
)			
Surveyor:	WILLIAM GIVENS		

Address:	301 S. MCLEAN ST.	
	BLOOMINGTON, 16.	
Present Owner:	THELMA RYDER	
Parcel Number:	21-04-456-007	
Historical Name:	BAKER HOUSE	
Construction Date:	CIRCA 1895	
Photo:	Roll No. <u>12</u> Frame No. <u>3</u>	
Architect/ Builder:		
Materials:	MOOD FRAME, SIDING ÉTRIM, BRICK FOUNDA	TIENÉ PIERS.
verall shape or plan, number of stories and roof shape: 5/DE GABLED, 2 STORY VICTORIAN WITH LARGE GABLE FRONT DORMER CENTERED DIEK PORCH Subsidiary Buildings:		
Condition: (See de	finition on reverse)	
	Excellent; Good;	Deteriorated
Describe major phys	ical changes from original construction:	
	<u> </u>	
· .	· · · · · · · · · · · · · · · · · · ·	
Potential National a. Individually	Register:	(yes/no) NO
b. As a part of a	le for potential designation - specify crit	(yes/no) YES
	wilding common, special or unique (one-of-a istorical associations.	-kind) in any regard and specify feature(s)
)		
Surveyor:///	1/4/AM BIVENS 8-22-90	

Address:	303 S. MCLEAN ST. BLOOMINGTON, IL.
Present Owner:	CARTER SUGS BANK
Parcel Number:	21-04-456-015
Historical Name:	
Construction Date:	CIRCA 1890
Photo:	Roll No. 12 Frame No. 4
Architect/ Builder:	
Materials:	WOOD FRAME, CLAPBOARDS ETRIM, BRICK FOUNDATION, BLOCK PIERS
erall shape or pr	lan, number of stories and roof shape: 1/2 STORY GABLE FRONT WITH HIPPED ROOF FLYL WIDTH PORCH
Subsidiary Building	gs:
Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction: PIERS REPLACED ON
- FRONT	PORCH.
Potential National	Register:
a. Individually	(yes/no)
h As a part of a	district (yes/no) // Sale for potential designation - specify criteria A, B, C, D, or combination of any.
	building common, special or unique (one-of-a-kind) in any regard and specify feature(s)
)	
Surveyor:	WILLIAM GIVENS

Address:	305 S. MCLEAN ST. BLOOMINGTON, FL.
Present Owner:	RUTH PUTMAN
Parcel Number:	21-04-456-016
Historical Name:	
Construction Date:	CIRCA 1890
Photo:	Roll No. 12 Frame No. 5
Architect/ Builder:	
Materials:	WOOD FRAME & TRIM, ARTIFICIAL SIDING, BRICK FOUNDATION, CHIMNEY & PIERS
overall shape or pl	an, number of stories and roof shape: IRREGULAR SHAPED //2
STORY C	ROSS GABLE VICTORIAN
Subsidiary Building	gs:
Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction:
Determinal Matrices	Pagintor:
Potential National a. Individually	(yes/no)
b. As a part of a	district (yes/no)
c. Explain rationa	are for potential designation opening error in, 2, 1, 1,
	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s)
)	•
Surveyor: W	1/LLIAM GIVENS

Address:	307 S. MCLEAN ST. BLOOMINGTON, IL.	•	
Present Owner:	THELMA RYDER		
Parcel Number:	21-04-456-017		
Historical Name:			
Construction Date:	<u>CIRCA 1890</u>		
Photo:	Roll No. 12 Frame No. 6		
Architect/ Builder:			
Materials:	WOOD FRAME CLAPBOARDS & TRIM. BRICK FOUNDATION, PLEAS & CHIMNEY	 	
Overall shape or p.	Overall shape or plan, number of stories and roof shape: 1/2 STORY, L-SHAPED CROSS GABLED LATE VICTORIAN WITH CRAFTSMAN DETAILED FRONT FORCH		
Subsidiary Building			
Condition: (See do	Excellent; Good; Deteriorated		
		z	
Describe major phys	sical changes from original construction: NRAP AROUND PORCH EITHER 2 UPDATED CIRCA 1905 - 1920		
AUVED OF	OF UM/ED CINCOT FLOO		
Potential National	Register:		
a. Individually	(yes/no)		
b. As a part of a district c. Explain rationale for potential designation - specify criteria A, B, C, D, or combination of any.			
	$C \notin D$		
Comments: Is the building common, special or unique (one-of-a-kind) in any regard and specify feature(s) and/or historical associations.			
)			
Surveyor:	WILLIAM GIVENS		

Address:	401 S. MCLEAN ST. BLOOMINGTON, IL.		•
Present Owner:	WALTER BECK		
Parcel Number:	21-04-458-011	. 46	
Historical Name:			
Construction Date:	CIRCA 1890		
Photo:	Roll No. 12 Frame No. 7		
Architect/ Builder:			
Materials:	WOOD FRAME & TRIM, ARTIFICIAL SIDING, CHIMNEY	BRICK FOUNDATION	(, PIERS &
CROSS GA	an, number of stories and roof shape: BLE VICTORIAN WITH DE	_/RREGULAR SHE OMINANT FRONT C	APED, 1/2 STORY
Subsidiary Building			
Condition: (See de	finition on reverse)		
Describe major phys	Excellent; Good		PHED
Potential National	Register:		
a. Individuallyb. As a part of ac. Explain rational	district ale for potential designation – specif	(yes/no) (yes/no) y criteria A, B, C, D, or com	NO oination of any.
Comments: Is the b			i specify feature(s)
Surveyor:Date:	WILLIAM GUENS		

Address:	403 S. MCLEAN ST.	
	BLOOMINGTON, IL.	
Present Owner:	ROBERT DEFRATES	
Parcel Number:	21-04-458-012	
Historical Name:		
Construction Date:	CIRCA 1895	
Photo:	Roll No. 12 Frame No. 8	
Architect/ Builder:		
Materials:	WOOD FRAME, SIDING F. TRIM.	BRICK FOUNDATION, CHIMNEY
verall shape or p		2 STORY GABLE FRONT DROOF PORCH
Subsidiary Building	ية:	
Condition: (See de	efinition on reverse)	
	Excellent Good	; Deteriorated
Describe major phys	sical changes from original construction	on: FRONT PORCH ENCOSED
		,
Potential National	Register:	
a. Individually		(yes/no) NO
b. As a part of a	district	(yes/no)
c. Explain ration	are for potential designation specif	direction in B, O, B, Or communication or any
<u> </u>		
	ouilding common, special or unique (one	e-of-a-kind) in any regard and specify feature(s)
)		
Surveyor:	WILLIAM G'VENS	

Address:	4045 MCLEAN ST. BLOOMINGTON, IL.	
Present Owner:	DAVID NEAL	
Parcel Number:	21-04-459-002	
Historical Name:		
Construction Date:	OIRCA 1895	
Photo:	Roll No. 12 Frame No. 9	
Architect/ Builder:		
Materials:	WOOD FRAME, CLAPBOARDS & TRIM. BRICK FOUNDATION & CHIMNEY.	
Overall shape or plan, number of stories and roof shape: 1/2 STORY GABLE FRONT		
Subsidiary Buildin	gs:	
Condition: (See d	lefinition on reverse)	
	Excellent; Good; Deteriorated	
Describe major phy	ORNER ADDED ON NORTH SIDE	
SHED D	ORMER ADVED ON HOLTH SIPP	
Potential National	Register:	
a. Individually	(yes/no)	
b. As a part of a	a district (yes/no)	
Comments: Is the	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) historical associations.	
)		
Surveyor:	WILLIAM GIVENS	

Address:	HOSS, MCLEAN SI. BLOOMINGTON, IL.
Present Owner:	THELMARYDER
Parcel Number:	21-04-458-013
Historical Name:	
Construction Date:	URCA 1870-80
Photo:	Roll No. 12 Frame No. 10
Architect/ Builder:	
Materials:	WOOD FRAME, CLAPBOARDS ÉTRIM. BRICK FOUNDATION ÉCHIMNEY
GABLE F	Lan, number of stories and roof shape: IRREGULAR SHAPED, 1/2 5785
Subsidiary Building	
Condition: (See de	efinition on reverse) Excellent; Good; Deteriorated
Describe major phys	Sical changes from original construction: A SER/ES OF 3 ADDITIONS A SUCT CREATING THE IRREGULAR FLAN
•	
Potential National	Register: (yes/mo)
a. Individuallyb. As a part of ac. Explain ration	(and the)
Comments: Is the land/or h	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) nistorical associations.
)	
Surveyor: //	VILLIAM GIVENS

Address:	407 S. MCLEAN ST. BLOOMINGTON, IL.		
Present Owner:	WILMA SPRAGUE		
Parcel Number:	21-04-458-014		
Historical Name:			
Construction Date:	CIRCA 1905-1930		
Photo:	Roll No. <u>/2</u> Frame No//_		
Architect/ Builder:			
Materials:	WOOD FRAME & SOME TRIM, ARTIFICIAL SIDING, BRICK CHIMNEY, FOUNDATION		
	É PORCH PIERS		
verall shape or pl	verall shape or plan, number of stories and roof shape: 2 STORY GABLE FRONT		
Subsidiary Building			
Condition: (See definition on reverse)			
•	Excellent; Good; Deteriorated		
Describe major phys	sical changes from original construction: <u>COVER-ALL SIDING VOB</u>		
Potential National a. Individually	Register: (yes/no) NO		
b. As a part of a			
(Explain factors	are for potential decadameter. Opening the second of the s		
	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) distorical associations.		
)			
Surveyor: //	MLIAM GIVENS		

Address:	503 S. MCLEAN ST. BLOOMINGTON, IL.
Present Owner:	BETH HAWKINS
Parcel Number:	21-04-460-016
Historical Name:	
Construction Date:	CIRCA 1890
Photo:	Roll No. 12 Frame No. 12
Architect/ Builder:	
Materials:	WOOD FRAME & SOME TRIM, BRICK FOUNDATION, PHERS & CHIMNEY. ARTIFICIAL.
MASSED F. Subsidiary Building	efinition on reverse)
Describe major phys	Excellent; Good; Deteriorated Sical changes from original construction:
Potential National a. Individually b. As a part of a c. Explain rational	(yes/no)
	wilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) istorical associations.
)	
Surveyor:	WILLIAM GIVENS 9-26-90
Date:	

Address:	505 S. MCLEAN ST. BLOOMINGTON, IL.	
Present Owner:	JEFFREY GIBSON	
Parcel Number:	21-04-460-017	
Historical Name:		
Construction Date:	<u>CIRCA 1870</u>	
Photo:	Roll No. /2 Frame No. 13	
Architect/ Builder:		
Materials:	WOOD FRAME & TRIM, AUMINUM SIDING, BRICK FOUNDATION & CHIMNEY	
verall shape or plan, number of stories and roof shape: 2 STORY L-SHAPED GABLE FRONT-AND-WWG, ISTORY WING		
Subsidiary Building		
Condition: (See de	efinition on reverse)	
Describe major physical ALTERED.	Excellent; Good; Deteriorated sical changes from original construction:5/D/M/6 APPL/ED , PSPCH DETA/LS MISSING OR COVERED BY 5/D/N/6	
Potential National	Register:	
a. Individually	(yes/no)	
c. Explain ration	ale for potential designation - specify criteria A, B, C, D, or combination of any.	
Comments: Is the building common, special or unique (one-of-a-kind) in any regard and specify feature(s) and/or historical associations.		
•		
Surveyor:	9-27-90	

Address:	506 S. MCLEAN ST.
	BLOOMINGTON, IL.
Present Owner:	WESLEY WYLTE
Parcel Number:	21-04-461-009
Historical Name:	
Construction Date:	CIRCA 1905-1930
Photo:	Roll No. 12 Frame No. 14
Architect/ Builder:	
Materials:	WOOD FRAME, ARTIFICIAL SIDING & TRIM, ROCK FACED BLOCK FOUNDATION, BRICK, & CONCRETE ON PORCH, BRICK, CHIMEY
verall shape or pl	Lan, number of stories and roof shape: RECTANGULAR SHAPED 1/2
Subsidiary Building	gs:
Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction: <u>ADDITION ON REAR</u> , FRONT
PORCH E	WOLDSED, COVER-ALL SIDING 30B.
Potential National	Register: (yes/no) ₩8
a. Individuallyb. As a part of a	district (yes/no) (/o
c. Explain ration	ale for potential designation - specify criteria A, B, C, D, or combination of any.
Comments: Is the and/or 1	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) historical associations.
Surveyor:	WILLIAM GIVEN

Address:	508 S, MCLEAN ST. BLOOMINGTON, IL.
Present Owner:	RUDY GALLOWAY
Parcel Number:	21-04-461-010
Historical Name:	
Construction Date:	_C/RCA 1870
Photo:	Roll No. 12 Frame No. 15
Architect/ Builder:	
Materials:	WOOD FRAME & TRIM, PARGETED FOUNDATION, ALUMINUM
verall shape or pl \[\frac{\mathcal{L} - \mathcal{H} \omega S}{\mathcal{S}} \] Subsidiary Building	an, number of stories and roof shape: 2 STORY, SIDE GABLED E FORM, WING ADDITION ON REAR.
•	efinition on reverse)
CONTICION: (Dec as	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction: 5/DING APPLIED,
	TION PARGETED
Potential National	Register: (yes/no) (//)
a. Individuallyb. As a part of a	district (yes/mo) 40
c. Explain ration	ale for potential designation - specify criteria A, B, C, D, or combination of any.
Comments: Is the and/or h	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) distorical associations.
)	
Surveyor: (x	MLIAM GIUENS

Address:	606 S. MCLEAN ST. BLOOMINGTON, IL.
Present Owner:	ROBERTREWERTS
Parcel Number:	21-04-463-007
Historical Name:	
Construction Date:	CIRCA 1900-1920 C
Photo:	Roll No. 12 Frame No. 16
Architect/ Builder:	
Materials:	WOOD FRAME, CLAPBOARDS & TRIM. ROCK FACED BLOCK, FOUNDATION & PORCH PIER
Subsidiary Building Condition: (See de	an, number of stories and roof shape:
Potential National	Register:
a. Individually b. As a part of a	(yes/no)
	uilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) istorical associations.
)	
Surveyor:	WILLIAM GIVENS 9-27-90

DEFINITIONS FOR CONDITION:

EXCELLENT - All original architectural details are apparently intact and major elements (foundations, walls, windows and roof) are in repair.

GOOD - Almost all of the elements characterizing "EXCELLENT" but missing some original details and requiring some work but not stabilization.

DETERIORATED - All or some major elements (foundations, walls, windows and roof) require replacement. Original architectural details may or may not still be present.

CRITERIA FOR EVALUATION OF NATIONAL REGISTER POTENTIAL:

The quality of significance in American history, architecture, archeology, engineering and culture is present in districts, sites, buildings, structures and objects that possess integrity of location, setting, design, materials, workmanship, feeling and association:

- A. that are associated with events that have made a significant contribution to the broad patterns of our history; or
- B. that are associated with the lives of persons significant in our past; or
- C. that embody the distinctive characteristics of a type, period or method of construction, or that represent the work of a master, or that possess high artistic values, or that represent a significant and distinguishable entity whose components may lack individual distinction; or
- D. that have yielded, or may be likely to yield, information important in prehistory or history.

	•	•	
Address:	103 N. EVANS ST. BLOOMINGTON, IL.		
Present Owner:	MICHAEL PETSAS		
Parcel Number:	21-04-432-003		
Historical Name:			
Construction Date:	CIRCA 1905-1920	The second secon	Lu (1
Photo:	Roll No. 12 Frame No. 22		
Architect/ Builder:		•	
Materials:	WOOD FRAME, CLAPBOAR FTRIM, BLOCK FOUND ON ENCLOSED FRONT	DATION, CEDAR S PORCH	HINGLE SIDIN
overall shape or pl	lan, number of stories and roof shape: SLED CRAFTSMAN WITH	RECTANGULARSA	APED, 2 STOR
Subsidiary Building	gs: NONE	,	
Condition: (See de	efinition on reverse)		
	Excellent; Good		_
Describe major phys	sical changes from original construction SIDING APPLI	n: <u>FRONT PORCH</u> ED	ENCLOSED,
Potential National	Pagistor:		
a. Individually	Negroce .	(yes/no) _/	10
b. As a part of a	district ale for potential designation – specify	(yes/no) criteria A, B, C, D, or combine	/
Comments: Is the band/or h	ouilding common, special or unique (one distorical associations. HOUSE /	-of-a-kind) in any regard and sp N NEED OF ATTENT RIORATED CONDITION	ecify feature(s)
Surveyor:	LIAM GWEKE		

Address:	203 S. EVANS ST.	
	BLOOMINGTON, IL.	
Present Owner:	DAVIDMILLER	
Parcel Number:	21-04-419-015	
Historical Name:	CHRISTIAN RIEBSAM	
Construction Date:	<u>CIRCA 1870</u>	
Photo:	Roll No. $/2$ Frame No. 23	
Architect/ Builder:		
Materials:	WOOD PRAME & TRIM, ASPHALT COMPOSITION ABBECTOS SIDING, BRICK FOUNDATION	
Subsidiary Building	an, number of stories and roof shape: <u> IRREGULAR SHAPED</u> , 2 5701 H SQUARE 35TORY HIPPED ROOF TOWER, CROSS GABLE ROO s: <u>NONE</u>	ey F
Condition: (See de	finition on reverse)	
	Excellent; Good; Deteriorated	
Describe major phys	ical changes from original construction: ASPHALT CONFOSITION	
5/DING,	APPLIED, MANY DETAILS MISSING OF COVERED	- ,
Potential National	Pogistor	
a. Individually	(yes/no) NO	
b. As a part of a	district (yes/no) (yes/no) le for potential designation - specify criteria A, B, C, D, or combination of any.	
c. Explain rationa	te for potential designation appears error in 1, 2, 0, 1,	
	uilding common, special or unique (one-of-a-kind) in any regard and specify feature(s)	
)		
Surveyor: W	<u>ULIAM GNENS</u>	

Address:	DOSS. EVANS ST. BLOOMINGTON, TL.		
Present Owner:	DAN GRAYBILL		
Parcel Number:	21-04-419-016		
Historical Name:			
Construction Date:			
Photo:	Roll No/2 Frame No24_		
Architect/ Builder:			
Materials:	BRICK, GASS AND ALUM FRONT FACADE, TILES	COVER TAXALET.	REMAINING
) Overall shape or pl	EXTERIOR WALLS ARE (lan, number of stories and roof shape: MMERCIAL BUILDING FLA	RECTANGULAR SH	HATED,/
Subsidiary Building			<u> </u>
Condition: (See de	efinition on reverse)		
	Excellent; Good1	; Deteriorated	
December major phy	rsical changes from original constructio	n: STOKE FRONT	WILLDOWS
E Doors	REPLACED.		
Potential National	. Register:	(yes/no)	NO
a. Individuallyb. As a part of ac. Explain ration	a district male for potential designation – specify	(yes/no)	ation of any.
Comments: Is the and/or	building common, special or unique (one historical associations.	e-of-a-kind) in any regard and sp	pecify feature(s)
Surveyor:	VILLIAM GIVENS	·	

Address:	DO8 S. EVANS ST. BLOOMINGTON,IL
Present Owner:	MARION JETTON
Parcel Number:	21-04-439-006
Historical Name:	
Construction Date:	
Photo:	Roll No. 12 Frame No. 25
Architect/ Builder:	
Materials:	WOOD FRAME & TRIM, ALUMINUM SIDING, BRICK FOUNDATION
verall shape or p	Lan, number of stories and roof shape: /RREGUAR SHAPED , / STORY,
GABLE ROOT	سو پر ادرسه س
Subsidiary Building	
Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction:
Potential National	Ponjeter'
a. Individually	(yes/no)
). As a most of o	· //
C. Explain radion	
Comments: Is the	building common, special or unique (one-of-a-kind) in any regard and specify feature(s)
)	
Surveyor: //	LLIAM GIVENS

Address:	304 S. EVANS ST.		
	BLDDMINGTON, IL.		
Present Owner:	LAWRENCE STOUT		
Parcel Number:	21-04-476-002		
Historical Name:		74	3.4
Construction Date:			
Photo:	Roll No. 12 Frame No. 26		The state of the s
Architect/ Builder:			
Materials:	MOOD FRAME, SIDING	ICK FOUNDAT	TON & PIERS
overall shape or pl	an, number of stories and roof shape:	RECTANGL	WAR SHAPED
2 STORY	GABLE FRONT WITH	HIP ROOF LOW;	ER PRONT PORCH
Subsidiary Building			
Condition: (See de	efinition on reverse)		-
	Excellent; Good <u>\</u>	; Deteriorated _	·
Describe major phys	sical changes from original construction	on:	·
Potential National	Register:		10
a. Individually			es/no)
b. As a part of a	district ale for potential designation - specif		es/no) YES or combination of any.
c. Explain ration	^		
	building common, special or unique (on	e-of-a-kind) in any rega	ard and specify feature(s)
and/or 1	nistorical associations.		
,		1.	•
Surveyor: ///	WIAM GIVENS	•	

Address:	403 S. EVANS ST. BLOOMINGTON, IL.		
Present Owner:	DAVID KANNADY	The state of the s	
Parcel Number:	21-04-459-017		
Historical Name:	G. EGAN HOUSE		
Construction Date:	1911		
Photo:	Roll No. 12 Frame No. 27		
Architect/ Builder:	A. PILSBURY		
Materials:	WOOD FRAME, CLAPBOARD	S ATION, PIERS & CHIMNEY	
verall shape or pl CRAFTSMAN Subsidiary Building	lan, number of stories and roof shape: <u>S</u> VWITH HIPPED ROOF & GABL gs: <u>GARAGE</u>	ED FULL WIDTH PORCH	
Condition: (See de	efinition on reverse)		
	Excellent; Good;	Deteriorated	
Describe major phys	sical changes from original construction: _		
Potential National	Register:		
a. Individuallyb. As a part of ac. Explain ration	ale for potential designation - specify crit	(yes/no) <u>NO</u> (yes/no) <u>YES</u> teria A, B, C, D, or combination of any.	
	290		
and/or IN THIS AND HOM Surveyor:	COMMUNITY WHO DESIGNED WES. A THEMATIC GROUPING	A-kind) in any regard and specify feature(s) INT MAS A PROMINENT ARCHITECT OF HIS WORK THAT REMAINS IN NTRIBUTING CONDITION SHOULD E CONSIDERED,	Kl& Kl
Date:	1 10 - 10	•	

Address:	405.5. EVANS ST. BLOOMINGTON, IL.	William Control of the Control of th
Present Owner:	KENNETH KASHIAN	
Parcel Number:	21-04-459-018	
Historical Name:		
Construction Date:	OIRCA 1911	
Photo:	Roll No. 12 Frame No. 28	
Architect/ Builder:		
Materials:	WOOD FRAME & TRIM, CEDAR SHINGLE SIDING.	BRICK FOUNDATION
Subsidiary Building Condition: (See de	IN WITH HIPPED ROOF & GABL	
Potential National	Register:	
a. Individuallyb. As a part of a	district ale for potential designation - specify criteri	(yes/no) // // / // // // // // // // // // //
Comments: Is the band/or h Surveyor: M Date:	ouilding common, special or unique (one-of-a-kinstorical associations. THE HOUSE AT IT BY PILSBURY. GIVEN THE SIELY THAT 40514 407 WENTER SAME SAME OF LEGERAL SAME SAME OF LEGERAL SAME OF LE	nd) in any regard and specify feature(s) 403 "ISKNOWN TO BE DESIGNED" MALARITIES IN FORM IT IS RE ASSO DONE BY THE DE BUILDER AT ABOUT E SAME TIME,

Address:	406 S. EVANS ST. BLOOMINGTON, IL.
Present Owner:	BEVERLY CAMPBELL
Parcel Number:	21-04-480-008
Historical Name:	
Construction Date:	
Photo:	Roll No. 12 Frame No. 29
Architect/ Builder:	
Materials:	NOOD FRAME, CLAPBOARDS & TRIM. BRICK FOUNDATION & CHIMNEY.
CRAFTSMAN	an, number of stories and roof shape: SQUARE SHAPED, 2 STORY WITH HIPPED ROOF AS: NOWE
•	efinition on reverse)
COLUMN (DOC 40)	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction: FRONT PORCH & STONE FLANTER
Potential National	Register:
a. Individually	(yes/no) <u>//O</u>
and/or h	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) instorical associations. COULD BE CONTRIBUTING IF FRONT
Surveyor:	RE RESTORED TO ORIGINAL APPEARANT. (SEE OTHER COMMENTS ON OJ-28-90 COCCU BE CONTRIBUTED. SHEET FOR 405.)

Address:	407 S. EVANS ST.		
	BLOOMINGTON, IL.		
Present Owner:	PAMELA PADRO		
Parcel Number:	21-04-459-019		
Historical Name:			
Construction Date:	CIRCA 1911		
Photo:	Roll No. 12 Frame No. 30		
Architect/ Builder:	· 		•
Materials:	WOOD FRAME & TRIM. CEDAR SHINGLE SUDING,	BRICK FUNDATION	
•	· · · · · · · · · · · · · · · · · · ·		
verall shape or pl	lan, number of stories and roof shape:	SQUARE SHAPED, 2 STOK, CABLED FULL WITH PORCH	Y
Subsidiary Building	IAN MITH MITEL FORE	CAPLED FULL WHATTION SI	
	efinition on reverse)	,	
COLUMN (OCO AL	Excellent; Good	; Deteriorated .	
Describe raior phys	sical changes from original construction:	•	
bescribe major phys	sical charges from original constructions		
		· · · · · · · · · · · · · · · · · · ·	
Potential National	Register:		
a. Individually		(yes/no) // // // // // // // // // // // // //	
b. As a part of ac. Explain rations	district ale for potential designation — specify cr	riteria A, B, C, D, or combination of any.	
· <u> </u>	CÉD		
	•	· · · · · · · · · · · · · · · · · · ·	
	ouilding common, special or unique (one-of distorical associations.	f-a-kind) in any regard and specify feature(s) 5 FOR 405 5. EVANS	
Surveyor:	WILLIAM 6/VENS		

Address:	503 S. EVANS ST. BLOOMINGTON, IL.
Present Owner:	MARY WILLS
Parcel Number:	21-04-461-008
Historical Name:	
Construction Date:	
Photo: ·	Roll No. 12 Frame No. 31
Architect/ Builder:	
Materials:	WOOD FLAME, CHAPBOARDS & TRIM, BRICK FOUNDATION & PORCH PIERS
overall shape or pl	an, number of stories and roof shape: PECTANGULAR SHAPED 1/2 6ABLE FRONT FAMILY WITH FULL WIDTH HIPPED FORCH
Subsidiary Building	s: <u>GARAGE & CARPORT</u>
Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction: 54/6HTLY PITCHED FLAT ROOF
CARPORT	BUILT RIGHT NEXT TO HOUSE OVER THE EXISTING
DRIVEWA	*************************************
Potential National	Register: (yes/no)
a. Individuallyb. As a part of a	district (yes/m) VES
c. Explain rationa	ale for potential designation - specify criteria A, B, C, D, or combination of any.
Comments: Is the and/or h	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) istorical associations.
Surveyor: W//	4-28-90

Address:	504 S. EVANS ST. BLOOMINGTON, IL.		
Present Owner:	HELEN ALDERMAN		
Parcel Number:	21-04-483-003		
Historical Name:			
Construction Date:			
Photo:	Roll No. <u>12</u> Frame No. <u>32</u>		
Architect/ Builder:			
Materials:	WOOD FRAME, ARTIFIC SIDING, PARGETED I BRICK CHIMATEY	FOUNDATION, BRICK.	PIERS ON PORCH
Verall shape or pl	an, number of stories and roof shape: ABLE ROOFED ORAFTS/	RECTANGULAR S UAN	HATED 2
Condition: (See de	efinition on reverse)		•
	Excellent; Good	; Deteriorated	
Describe major phys	Sical changes from original construction	on: COVER-ALL	SIDING CE
Potential National	Register:		
a. Individually		(yes/no)	NO
b. As a part of a c. Explain rations	district ale for potential designation – specif	(yes/no) _ y criteria A, B, C, D, or combin	ation of any.
Commental To the h	ouilding common, special or uniqué (on	e-of-a-kind) in any regard and s	specify feature(s)
	distorical associations.	e of a kirkly in any regard and o	,
)	•		
Surveyor:	114/AM 61/ESE 9-28-90		

Address:	504/5 S. EVANS ST. BLOOMINGTON, IL.
Present Owner:	JAMES DIDDAMS
Parcel Number:	21-04-483-004
Historical Name:	
Construction Date:	
Photo:	Roll No. 12 Frame No. 33
Architect/ Builder:	
Materials:	WOOD FRAME, TRIM ESOME SIDING, SOME ARTIFICIAL SIDING, FRICK FOUNDATION
verall shape or pl VICTORIAL Subsidiary Building	an, number of stories and roof shape: //z 570RY CABLE FRONT N MITH LOWER ENCLOSED FULL WIDTH FORCH s:
Condition: (See de	finition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	ical changes from original construction: FORCH ENCLOSED
ARTIFIC	IAL SIDING APPLIED
Potential National	Register:
a. Individually	(yes/no)
b. As a part of a	district (yes/no) (yes/no) le for potential designation - specify criteria A, B, C, D, or combination of any.
c. Explain rationa	Te for potential designation specify effected in, b, o, b, of companies of any
	uilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) istorical associations.
Surveyor:	WILLIAM GIVENS

Address:	506 S. EVANS ST. BLOOMINGTON, IL.
Present Owner:	MARGARETGRIFFIN
Parcel Number:	21-04-483-005
Historical Name:	
Construction Date:	CIRCA 1874-90
Photo:	Roll No. 12 Frame No. 34
Architect/ Builder:	
Materials:	WOOD FRAME, CLAPBOARDS & TRIM, BRICK FOUNDATION & CHIMNEY PARGETED
	an, number of stories and roof shape: //e STORY GABLE FRONT
Subsidiary Building	1/2 1/2
Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction:
Potential National	Register'
a. Individually	(yes/no) NO
b. As a part of a	مسرم مواد را المراجعة عن ا
c, Explain rationa	C
	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) distorical associations. COMMON. HOUSE IS FAST APPROACHING ADETERIORATED CONDITION,
Surveyor: //	114/AM 610ENS

Address:	508 S. EVANS ST.
	BLOOMINGTON, IL.
Present Owner:	ROBERT KNAPP
Parcel Number:	21-04-483-006
Historical Name:	
Construction Date:	
Photo:	Roll No. 12 Frame No. 35
Architect/ Builder:	
Materials:	NOOD FRAME & SOME TRIM, ARTIFICIAL SIDING & TRIM, BLOCK FOUNDATION, SOME STUCCO ON FORCH
verall shape or pl	an, number of stories and roof shape: <u>CROSS SHAPFD</u> 2. STORY BE WITH ENCLOSED FLAT ROOFED FORCH
Subsidiary Building	·
•	
Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction: PORCH ENCLOSED &
ARTIFICIAL	L SIDING APPLIED
Potential National	A la
a. Individuallyb. As a part of a	(yes/no) // (yes/no) // (yes/no)
b. As a part of ac. Explain rational	ale for potential designation - specify criteria A, B, C, D, or combination of any.
	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) distorical associations.
)	EBOOLIGHT RESERVED TO THE TANK
Surveyor:Date:	WILLIAM GIVENS 9-28-90

Address:	5081/2 S. EVANSST. BLOOMINGTON, IL		
Present Owner:	KENNETHBROWN		
Parcel Number:	21-04-483-007		
Historical Name:			
Construction Date:	CIRCA 1875-80		
Photo:	Roll No. 12 Frame No. 36		
Architect/ Builder:			
Materials:	WOOD FRAME & TRIM, ARTIFICIAL SIDING, BRICK FOUNDATION & PARGETED CHIMNEY		
overall shape or pl	Lan, number of stories and roof shape: //a 570RY GABLE-FRONT-		
•	TH FULL WIDTH PORCH & LOWER REAR ADDITION		
Subsidiary Building			
Condition: (See de	Excellent; Good; Deteriorated		
Describe major phys	sical changes from original construction:		
Potential National	Register:		
a. Individually b. As a part of a district c. Explain rationale for potential designation - specify criteria A, B, C, D, or combination of any.			
	$C \neq D$		
Comments: Is the building common, special or unique (one-of-a-kind) in any regard and specify feature(s) and/or historical associations. THE COH SIDED THE BUILDING IS STILL A GOOD EXAMPLE OF THE KIND HOUSE CONSTRUCTED FOR THE WORKING Surveyor: WILLIAM SIVENS CLASS. Date: 10-30-90			

Address:	510 S. EVANS ST. BLOOMINGTON, IL.	
Present Owner:	RICE RENTALS	
Parcel Number:	21-04-483-008	型型
Historical Name:		
Construction Date:	CRCA 1900-1920	
Photo:	Roll No. 12 Frame No. 37	
Architect/ Builder:		·
Materials:	WOOD FRAME, CLAPBO	DATION & PIERS
verall shape or pl MASSED 1 Subsidiary Building		1/2 STORY, SIDE GABLED NOED ROOF OVER FULL WIDTH PERCH
·	ofinition on reverse)	
CORRECTION: (See as	Excellent; Good	; Deteriorated
Describe major phys		on:
Potential National	Register:	
a. Individually		(yes/no)
b. As a part of a	district	y criteria A, B, C, D, or combination of any.
C. Explain factor	C & D	
Comments: Is the	building common, special or unique (on historical associations.	ne-of-a-kind) in any regard and specify feature(s)
)		
Surveyor:	VILLIAM GIVENS	

	•	•	
Address:	512 S. EVANS ST. BLOOMINGTON, IL	ti i	
Present Owner:	BERNARD HEMMELE		
Parcel Number:	21-04-483-009		
Historical Name:			
Construction Date:	CIRCA 1900-1920	-	
Photo:	Roll No. 13 Frame No. 0		
Architect/ Builder:			
Materials:	WOOD FRAME & SOME TRIM, ARTIFICIAL SIL LOOK FOUNDATION,	DING É TRIM FL BRICK CHIMNEY	46 STONE
Subsidiary Building	lan, number of stories and roof shape: _/ WITH LOWER GABLED	1/2 STORY GABLE	FRONT
Condition: (See de	efinition on reverse)		
•	Excellent; Good;	Deteriorated	
Describe major phys	sical changes from original construction:	COUER-ALL SIDII	16 JOF,
Potential National	Register:	(yes/no))
a. Individuallyb. As a part of a	district	(yes/no)	2
c. Explain ration	ale for potential designation - specify cr	iteria A, B, C, D, or combination o	of any.
Comments: Is the and/or 1	building common, special or unique (one-of	-a-kind) in any regard and specify	feature(s)
)		•	
Surveyor:	WILLIAM GIVENS		

Address:	514 S. EVANS ST. BLOOMINGTON, IL.				
Present Owner:	ERWIN RUITHMETER				
Parcel Number:	21-04-483-010				
Historical Name:					
Construction Date:	<u>CIRCA 1900-1920</u>				
Photo:	Roll No. <u>13</u> Frame No. <u>1</u>				
Architect/ Builder:					
Materials:	WOOD FRAME, CLAPBOARDS & TRIM, PARGETED FOUNDATION				
verall shape or pl	verall shape or plan, number of stories and roof shape: / STORY CROSS GABLED CRAFTSMAN WITH DOMINANTIFONT GABLE, LOWER FULL WIDTH FORCH.				
•	efinition on reverse)				
	Excellent; Good; Deteriorated				
	sical changes from original construction: FOUNDATION PARGETED,				
Potential National	Register:				
a. Individually	(yes/no)				
b. As a part of a district c. Explain rationale for potential designation - specify criteria A, B, C, D, or combination of any.					
Comments: Is the	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) historical associations.				
)					
Surveyor:Date:	NILLIAM BIVENS 10-30-90				

		·
Address:	516 S. EVANS ST.	
	BLOOMINGTON, IL	
Present Owner:	GARMON TAYLOR	
Parcel Number:	21-04-483-011	
Historical Name:		
Construction Date:	CIRCA 1900-1920	
Photo:	Roll No. 13 Frame No. 2	
Architect/ Builder:		
Materials:	NOOD FRAME ÉSOME TRIM, ARTIFICIAL SIDI	VG, BRICK CHIMNEY & FOUNDATION
overall shape or p	lan, number of stories and roof shape: 171/ FNCLOSED GABLET	1/2 STORY GABLE FRONT
Subsidiary Buildin		
Condition: (See d	efinition on reverse)	
	Excellent; Good	Deteriorated
Describe major phy	sical changes from original construction:	PORCH ENCLOSED,
Potential National	Register:	
a. Individuallyb. As a part of ac. Explain ration	district ale for potential designation - specify o	(yes/no)
	building common, special or unique (one-chistorical associations.	of-a-kind) in any regard and specify feature(s)
,	WINNA GIVENS	
Supplications (//////////////////////////////////////	

DEFINITIONS FOR CONDITION:

EXCELLENT - All original architectural details are apparently intact and major elements (foundations, walls, windows and roof) are in repair.

GOOD - Almost all of the elements characterizing "EXCELLENT" but missing some original details and requiring some work but not stabilization.

DETERIORATED - All or some major elements (foundations, walls, windows and roof) require replacement. Original architectural details may or may not still be present.

CRITERIA FOR EVALUATION OF NATIONAL REGISTER POTENTIAL:

The quality of significance in American history, architecture, archeology, engineering and culture is present in districts, sites, buildings, structures and objects that possess integrity of location, setting, design, materials, workmanship, feeling and association:

- A. that are associated with events that have made a significant contribution to the broad patterns of our history; or
- B. that are associated with the lives of persons significant in our past; or
- C. that embody the distinctive characteristics of a type, period or method of construction, or that represent the work of a master, or that possess high artistic values, or that represent a significant and distinguishable entity whose components may lack individual distinction; or
- D. that have yielded, or may be likely to yield, information important in prehistory or history.

Parcel Number: Historical Name:	203 N. CLAYTON ST BLOOMINGTON, IL. MICHAEL TUTTLE 21-04-430-006		
Construction Date: Photo: Architect/ Builder:			
Materials:	WOOD FRAME & TRIM, ARTIFICIAL SIDING, I		
Overall shape or posterior of the Subsidiary Building	lan, number of stories and roof shape: WWTH HIPPED ROOF, CAR gs:	2 1/2 STORY SQUAR	RE SHAPEL DTH POXIH
Condition: (See d	efinition on reverse)		,
	Excellent; Good	; Deteriorated	
Describe major phy	sical changes from original construction	: SIDING APPLIED	<u>></u>
Description National	Pogistor		
Potential National a. Individually	Register.	(yes/no)	
h As a part of a	district ale for potential designation - specify	(yes/no) (yes/no) criteria A, B, C, D, or combination o	of any.
			·
Comments: Is the and/or	building common, special or unique (one- historical associations.	-of-a-kind) in any regard and specify	feature(s)
Surveyor:	MULIAM GIVENS		

Address:	103 S. CLAYTON ST. BLOOMINGTON, IL.
Present Owner:	HAROLDBALAGNA
Parcel Number:	21-04-435-006
Historical Name:	
Construction Date:	<u>CIRCA 1900-1920</u>
Photo:	Roll No. 13 Frame No. 4
Architect/ Builder:	
Materials:	NOOD FRAME, CLAPBOARDS &TRIM. BRICK FOUNDATION & CHIMNEY
Overall shape or pl 4 SQUARE Subsidiary Building	an, number of stories and roof shape: 2/2 STORY CRAFTSMAN HIPPED CENTRAL BLOCK, GABLED FRONT se:
Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction:
·	
Potential National	1/6
a. Individually b. As a part of a	district (yes/no) NO (yes/no) NES
c. Explain ration	ale for potential designation - specify criteria A, B, C, D, or combination of any.
	<u>C</u>
Comments: Is the land/or h	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) distorical associations.
)	
Surveyor: W/	WIAM 610ENS

Address:	104 S. CLAYTON ST. BLOOMINGTON, IL.
Present Owner:	DOROTHY LYONS
Parcel Number:	21-04-436-002
Historical Name:	
Construction Date:	CIRCA 1875-95
Photo:	Roll No. 15 Frame No. 3
Architect/ Builder:	
Materials:	WOOD FRAME & SOME TRIM, ARTIFICIAL SIDING, BRICK CHIMNEY, PARGETED
Overall shape or pi GABLE F Subsidiary Building	FOUNDATION lan, number of stories and roof shape: 25TORY, L-5HATTO RENT-AND-WING gs: GARAGE ATTACHED
	efinition on reverse)
	Excellent; Good; Deteriorated
	PRIME TO DELLA PEDIALED
Describe major phy	sical changes from original construction: ORKONAL PORCH REPLACED
COVEK-ALL	SDING JOB, GARAGE ADDED
Potential National	Register: (yes/no) 10
a. Individuallyb. As a part of a	(yes/no) (yes/no)
c. Explain ration	nale for potential designation - specify criteria A, B, C, D, or combination of any.
Comments: Is the and/or	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) historical associations.
Surveyor:	WILLIAM EXUENS

•				
Address:	203 S. CLAYTON SI. BLOOMINGTON, IL.		i	
Present Owner:	SCOTT ROUTLEY			1
Parcel Number:	21-04-439-010			ä
Historical Name:				
Construction Date:	: C, 1900 - 1928			
Photo:	Roll No. 13 Frame No. 5			19 19 (19) 10 (19)
Architect/ Builder:				
Materials:	WOOD FRAME CLAPBOH	NDATION &	HIMNEY.	
Overall shape or WITH HIPPE Subsidiary Buildi	plan, number of stories and roof shape DROXF & MER GABLE ngs:	: <u>2 STORY (</u> ED FULL NIDTA	PRONT POR	45Q OARE CH
Condition: (See	definition on reverse)	·		
	Excellent; Good	; Deteriorat	:ed	
Describe major ph	nysical changes from original construc	tion:		
Potential Nation	al Register:			,
T., 31 = 3., a11sr		•	(yes/no)	
	a district onale for potential designation - spec	ify criteria A, B, C,	(yes/no) /FS D, or combination of a	any.
	C & D			
Comments: Is th	ne building common, special or unique (r historical associations.	(one-of-a-kind) in any	regard and specify fea	ature(s)
)				
Surveyor:	WILLIAM 6/UENS			

Address:	204 S. CLAYTON ST. BLOOMTNGTON, IL.
Present Owner:	
Parcel Number:	21-04-440-006
Historical Name:	
Construction Date:	1890 - 1910
Photo:	Roll No. <u>/3</u> Frame No. <u>6</u>
Architect/ Builder:	
Materials:	WOOD FRAME & TRIM, ASPHALT COMPOSITION SIDING, BRICK. PIERS & FOUNDATION
L-SHAPED	an, number of stories and roof shape: 2/2 STORY
Subsidiary Building Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major physical NOT OKIG	sical changes from original construction: <u>SIDING APPLIED</u> , BALLUSTRAD
Potential National	Register: (yes/mo)
h As a part of a	district (yes/no) ale for potential designation - specify criteria A, B, C, D, or combination of any.
and/or)	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) instorical associations.

Address:	405 S. CLAYTON ST. BLOOMINGTON, IL.		
Present Owner:	CAROLYN RUST		
Parcel Number:	21-04-480-006		
Historical Name:			
Construction Date:	CIRCA 1895		<u>\$</u>
Photo:	Roll No. 13 Frame No. 8		
Architect/ Builder:			
Materials:	NOOD FRAME & TRIM, BRICK FOUNDATION, VI	NYL SIDING	
SWISS CHALE Subsidiary Building	ET INFLOFICED VICTORIAN	2/2 STORY SIDE GAB V WITH IRREGULAR FRO	NT FAC
	Excellent; Good	_; Deteriorated	
_	sical changes from original construction	: SIDING APPLIED, FI	RONT.
Potential National a. Individually b. As a part of a c. Explain ration	district	(yes/no) // // // // // // (yes/no) // // // // // // // // // // // // //	my.
·		<u> </u>	
Comments: Is the	building common, special or unique (one-	of-a-kind) in any regard and specify feat	ture(s)
and/or 1	historical associations.		
,			
Surveyor:	MLIAM GIVENS		

Address:	407 S. CLAYTONST. BLOOMINGTON, IL.
Present Owner:	CHARLESKAUFMAN
Parcel Number:	21-04-480-007
Historical Name:	
Construction Date:	CKCA 1880-1890
Photo:	Roll No. 13 Frame No. 9
Architect/ Builder:	
Materials:	NOODFRAME & TRIM, ARTIFICIAL SIDING, BRICK FOUNDATION, FIERS & CHIMNE
_GAMBR	lan, number of stories and roof shape: L-SHAPFD 2.570RY WITH EL ROOF gs: GARAGE
Subsidiary Buildin	
Condition: (See d	efinition on reverse)
Describe major phy	Excellent; Good; Deteriorated sical changes from original construction:
Potential National	
a. Individuallyb. As a part of ac. Explain ration	(yes/no) (ye
·	
Comments: Is the and/or	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) historical associations.
) .	
Surveyor:	MILLIAM GIVENS

Address:	409 S. CLAYTON ST. BLOOMINGTON, IL.
Present Owner:	WILLIAM GIOMI
Parcel Number:	21-04-480-013
Historical Name:	
Construction Date:	ORCA 1900-1920
Photo:	Roll No/3 Frame No/O
Architect/ Builder:	
Materials:	WOOD FRAME & SOME TRIM, ARTIFICIAL SIDING, BRICK PIERS & FOOKDATION
overall shape or p	HOUNDHION lan, number of stories and roof shape: // STORY CROSS GABLE MT SIDE GABLE & EXTENDED ROOF OVER PORCH gs:
Substantly 2	definition on reverse)
Condition: (See d	Excellent; Good; Deteriorated
Describe major phy	rsical changes from original construction: ARTIFICIAL SIDING
D	Pogistor!
Potential National	(yes/no)
_	(yes/no) (ye
Comments: Is the and/or	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) historical associations.
Surveyor:	WILLIAM GIVENS

Address:	SOLS. CLAYTON ST. BLOOMINGTON, IL.
Present Owner:	AMY DAVIS
Parcel Number:	21-04-483-015
Historical Name:	
Construction Date:	CIRCA 1875
Photo:	Roll No. /3 Frame No. //
Architect/ Builder:	
Materials:	WOOD FRAME & TRIM, FRICK FOUNDATION, PIERS & CHIMNEY, ACTIFICIAL SUNG
	Lan, number of stories and roof shape: L-SHAFFD 25TORY NITH
	SS:
•	efinition on reverse)
(= 1	Excellent; Good; Deteriorated
Describe major phy	sical changes from original construction: <u>SIDING APPLIED</u> , PORCH
<u>. </u>	
Potential National a. Individually	Register: (yes/no)
	district (yes/no)
Comments: Is the and/or	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) historical associations.
Surveyor:	WILLIAM GIVENS

Address:	SOD. S. CLAYTON BLOOMINGTON, IL
Present Owner:	DAVIDSCHUMACHER
Parcel Number:	21-04-484-001
Historical Name:	JOHN M. HAMILTON HOUSE
Construction Date:	CIRCA 1872
Photo:	Roll No. 13 Frame No. 28
Architect/ Builder:	
Materials:	WOOD FRAME, CHAPBOARDS FIRM. BRICK FOUNDATION & CHIMNEY.
Subsidiary Building	Han, number of stories and roof shape: \(\frac{\frac{12}{12}}{12} \frac{12}{12} \frac
Describe major phys	sical changes from original construction:
,	
Potential National	Register: (yes/no) YES (LISTED 1978)
a. Individually b. As a part of a	district (yes/no) YES
c. Explain ration	ale for potential designation - specify criteria A, B, C, D, or combination of any.
	A, B & C
and/or 1	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) historical associations. OUTSTANDING & ORNATE EXAMPLE OF A HON HOUSE FORM. HAMILTON WAS A LAWYER-POLITICIAN WHO WAS TED TO THE STATE SENATE IN 1876, LIEUTENANT GOVERNOR TO AND SERVED AS GOVERNOR FOR 18 MONTHS BEXING 1883 & 84.
Surveyor:	WILLIAM GIVENS HELIUED IN THE HOUSE FROM 1872 UNTIL 1883 WHEN 4EPENDINE C-VEDRICE

Address:	503 S. CLAYTON ST.	
	BLOOMINGTON, IL.	
Present Owner:	PATRICKWENDELL	
Parcel Number:	21-04-483-016	. 3
Historical Name:	- Annual Control of the Control of t	
Construction Date:	e: <u>CIRCA</u> 1875	
Photo:	Roll No. 13 Frame No. 12	e caraci
Architect/ Builder:		
	<u> </u>	•
Materials:	WOOD FRAME & TRIM, ARTIFICIAL SUDING, BRICK FOUNDATION, PIER	35€
	CHIMNEY	
overall shape or p	plan, number of stories and roof shape: 2 STORY GABLE FR WITH LOWER GABLED FULL WIDTH PORCH	CONT_
Subsidiary Buildir		<u> </u>
•	e definition on reverse)	
CONTICION. (CCC.)	Excellent; Good; Deteriorated	
	·	PAETE AN
Describe major phy	physical changes from original construction: 5/D/NG AFFILED, C	XAT /S/VIH
STYLE	= PORCH ADDED AFTER 1900,	
	1 Destation	,
Potential National	(100 (10)	·
a. Individuallyb. As a part of a	fordistrict (yes/no)	
c. Explain ration	ionale for potential designation - specify criteria A, B, C, D, or combination of a	ny.
·		
Comments: Is the and/or	he building common, special or unique (one-of-a-kind) in any regard and specify fea or historical associations.	ture(s)
-		
Controvers	11111 1AM GIVENS	

Address:	505 S. CLAYTON
	BLOOMINGTON, IL
Present Owner:	APRILTAKEUCHI
Parcel Number:	21-04-483-017
Historical Name:	
Construction Date:	CIRCA 1875-80
Photo:	Roll No/3 Frame No/3
Architect/	
Builder:	
Materials:	WOOD FRAME ÉSOME
	TRIM, ARTIFICIAL SIDING, BRICK FOUNDATION GCHIMNEY, CONCRETE PORCH
	& CHIMNEY, CONCRETE FORCH
erall shape or pl	Lan, number of stories and roof shape: / 570RY GABLE FRONT
FAMILY	
Subsidiary Building	gs:
Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction: <u>COVER-ALL SIDING JOB</u> ,
	PORCH REPLACED
Potential National	Register:
a. Individually	(yes/no) <u>NO</u>
b. As a part of ac. Explain ration	district (yes/no)ale for potential designation - specify criteria A, B, C, D, or combination of any.
<u></u>	
	building common, special or unique (one-of-a-kind) in any regard and specify feature(s)
and/or t	nistorical associations.
Surveyor:	WILLIAM GIVENS
Date:	10-31-90

Address:	506 S. CLAYTON
	BLOOMINGTON, IL.
Present Owner:	RALPH CHAMBERS
Parcel Number:	21-04-484-002
Historical Name:	
Construction Date:	CIRCA 1875-85
Photo:	Roll No. 13 Frame No 27
Architect/ Builder:	
Materials:	NOOD FRAME & SOME TRIM, ARTIFICIAL SIDING, BRICK FOUNDATION & CHIMNE)
-	
overall shape or p	lan, number of stories and roof shape: <u>L-5HAPED</u> 25TORY RONT-AND-WING WITH LOWER REAR ADDITION
Subsidiary Buildin	2000
	efinition on reverse)
COMMITTION: (See a	Excellent; Good; Deteriorated
	sical changes from original construction: FRONT FORCH ENCLOSED
Describe major phy	THE SIDING JOB.
COVE	
Potential National	Register:
a. Individually	(yes/no) // (yes/no) // (yes/no)
b. As a part of ac. Explain ration	nale for potential designation - specify criteria A, B, C, D, or combination of any.
Comments: Is the and/or	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) historical associations.
	·
Surveyor:	WILLIAM E. GIVENS

Address:	507/3 S. CLAYTON
	BLOOMINGTON, IL
Present Owner:	EVELYN WAFZIGER
Parcel Number:	21-04-483-019
Historical Name:	
Construction Date:	<u> 1900 - 1920 </u>
Photo:	Roll No. 13 Frame No. 15
Architect/ Builder:	
Materials:	MOOD FRAME & TRIM, ARTIFICIAL SIDING, BLOCK FOUNDATION, BRICK CHIMNE)
Overall shape or p SHAFTSMA Subsidiary Building	lan, number of stories and roof shape: //2 STORY, SIDE GABLED WITH SHED ROOFED DORMER & ENCLOSED FRONT PORCH gs:
Condition: (See d	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phy	Sical changes from original construction: PARCH ENCLOSED, CONFR-AC
Potential National	(yes/no)
	(yes/no)
Comments: Is the and/or	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) historical associations.
Surveyor:	WILLIAM GIVENS

Date:

Address:	508 S. CLAYTON ST. BLOOMINGTON, IL.		
Present Owner:	DRAKE FLESSNER		
Parcel Number:	21-04-484-003		
Historical Name:			
Construction Date:	CIRCA 1900 - 1920		
Photo:	Roll No. 13 Frame No. 26		
Architect/ Builder:			
Materials:	WOOD FRAME, CLAPBOARDS ÉTRIM. BRICK FOUNDATION É PIERS		
overall shape or p	lan, number of stories and roof shape: 2 STORY, HIPPED ROOF E WITH GABLED DORMER & FULL WIDTH OPEN PORCH		
Subsidiary Buildin			
Condition: (See d	efinition on reverse)		
	Excellent; Good; Deteriorated		
Describe major phy	sical changes from original construction:		
D. Control Martingal	Pogistor*		
Potential National a. Individually	(yes/no)		
b. As a part of a district c. Explain rationale for potential designation - specify criteria A, B, C, D, or combination of any.			
Comments: Is the and/or	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) historical associations.		
Surveyor:	WILLIAM GIVELLS		

Address:	509 S. CLAYTON ST.
	BLOOMINGTON, IL.
Present Owner:	MYROW CRUTCHER
Parcel Number:	21-04-483-020
Historical Name:	
Construction Date:	1900 - 1920
Photo:	Roll No/3 Frame No/6
Architect/ Builder:	
Materials:	WOOD FRAME & SOME TRIM, ARTIFICIAL SIDING, BRICK FOUNDATION & CHIMNE
Overall shape or p	plan, number of stories and roof shape: / STORY GABLE FRONT
Subsidiary Buildin	
	definition on reverse)
Colateron	Excellent; Good; Deteriorated
•	COVER-ALL SIDING JOB.
Describe major phy	ysical changes from original construction: <u>COVER-ALL</u> SIDING JOES,
FRONT	OKOH MITENED OX NET CARL
Potential Nationa	(yes/no)
a. Individuallyb. As a part ofc. Explain ratio	a district (yes/no)
Comments: Is the	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) historical associations.
Surveyor:	WILLIAM GIVENS
<u></u>	

)		
Address:	510:510% S. CLAYTON BLOOMINGTON, IL.	
Present Owner:	LAND TRUST CORN BELT BANK	
Parcel Number:	21-04-484-004	
Historical Name:		
Construction Date	: CIRCA 1980	
Photo:	Roll No. 13 Frame No. 25	
Architect/ Builder:		
Materials:	WOOD FRAME & TRIM,	
: .	PLYNOOD SIDING CONCRETE FOUNDATIO	
verall shape or p	plan, number of stories and roof shape:	2 STORY, AIPPED POOF
CONTEMPE	RARY 4 UNIT APARTMEN	IT BUILDINGS
Subsidiary Buildi	ngs:	
Condition: (See	definition on reverse)	
	Excellent; Good;	Deteriorated
Describe major ph	ysical changes from original construction:	
		<u> </u>
Potential Nationa	l Register:	1/0
a. Individually	At about at	(yes/no) // // (yes/no)
b. As a part ofc. Explain ratio	a district nale for potential designation – specify criter	· · · · · · · · · · · · · · · · · · ·
	building common, special or unique (one-of-a-k historical associations.	aind) in any regard and specify feature(s)
)		
	MULARA -ILI-AK	
Surveyor:	WILLIAM 61UENS	

Address:	511 S. CLAYTON ST. BLOOMINGTON, IL.
Present Owner:	DANIEL PENN
Parcel Number:	21-04-483-021
Historical Name:	
Construction Date:	CIRCA 1900-1920
Photo:	Roll No. 13 Frame No. 17
Architect/ Builder:	
Materials:	NOOD FRAMEÉSOME TRIM. BRICK FOUNDATION É CHIMNEY, ARTIFICIAL SIDING
overall shape or pi	lan, number of stories and roof shape:/ <i>STORY GABLE FRONT</i>
Subsidiary Building	gs: GARAGE
Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phy	sical changes from original construction:
Potential National a. Individually	(yes/no)
	district (yes/no) wale for potential designation - specify criteria A, B, C, D, or combination of any.
C. Implain racio	
<u> </u>	
Comments: Is the and/or	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) historical associations.
,	
Surveyor:	WILLIAM GIVENS

′			
Address:	511/2 S. CLAYTON BLOOMINGTON, IL.		•
Present Owner:	JOHN KAUFMAN		
Parcel Number:	21-04-483-022	Niki Maria	
Historical Name:			
Construction Date:	CIRCA 1900-1920	And the state of t	
Photo:	Roll No. <u>13</u> Frame No. <u>18</u>		1810 8 ±
Architect/ Builder:			
Materials:	NOOD FRAME & WINDON ARTIFICIAL SIDING, &	WS, RICK FOUNDATION & PAK	CETEL)
overall shape or p		RECTANGULAR SHAPED PAFTSMAN?	(570R)
Subsidiary Buildin	ıgs:		
Condition: (See d	definition on reverse)		
	Excellent; Good		حد و ا
Describe major phy FRONT W	vsical changes from original constructions VNDOW NOT OXIONNAL	: COVER-ALL SIDING. DETAILS MISSINGOR (JOP, POVERED.
Potential National	Register:		
a. Individually	1000000	(yes/no)	
b. As a part of ac. Explain ration	n district nale for potential designation - specify o	(yes/no)() criteria A, B, C, D, or combination of an	у.
	building common, special or unique (one-ohistorical associations.	of-a-kind) in any regard and specify feat	ure(s)
Surveyor: //	VILLAM GIUENS		

Address:	SID S. CLAYTON ST. BLOOMINGTON, IL.		
Present Owner:	LATNEY BROOKS		
Parcel Number:	21-04-484-005		
Historical Name:			
Construction Date:	CIRCA 1895		
Photo:	Roll No. <u>13</u> Frame No. <u>23</u>		
Architect/ Builder:	AGO MA A THE SAME AND		
Materials:	WOOD FRAME & TRIM, ARTIFICIAL SIDING, SOME PLYWOOD SIDING, BRICK		
578RY 6	an, number of stories and roof shape: RECTANGULAR SHAPED, 1/2 SABLE FRONT FAMILY (VICTORIAN COTTAGE)		
Subsidiary Building	s:GARAGE OR SHED AT REAL		
Condition: (See de	finition on reverse)		
	Excellent; Good; Deteriorated		
Describe major phys	ical changes from original construction: 5/DING APPLIED, FRONT		
PORCH EN	(CLOSED		
Potential National	Register:		
a. Individually	(yes/no) <u>//</u>		
b. As a part of a district (yes/no)			
	wilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) istorical associations.		
Surveyor: ///. Date:	11-5-90		

) .

Address:	513 S. CLAYTON ST. BLOOMINGTON, IL.
Present Owner:	KAREN MCCONNELL
Parcel Number:	21-04-483-023
Historical Name:	
Construction Date:	CIRCA 1900-1928
Photo:	Roll No. 13 Frame No. 19
Architect/ Builder:	
Materials:	NOOD FRAME & TRIM, ROCK FACED BLOCK FOUNDATION, BRICK CHIMNEY ARTIFICIAL SIDING
verall shape or pl	an, number of stories and roof shape: 1/2 STORY, RECTANGULAR
Subsidiary Building	ABLE FRONT ORAFTSMAN.
	finition on reverse)
CORRECTOR: (See de	Excellent; Good; Deteriorated
	ical changes from original construction: SIDING AFFLIED, FROMT
	CLOSED
10xul 2	
Potential National	Register:
a. Individually	(yes/no) NO
b. As a part of ac. Explain rationa	district (yes/no) <u>XO</u> le for potential designation - specify criteria A, B, C, D, or combination of any.
<u> </u>	
	wilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) istorical associations.
)	
Surveyor: //	JILLIAM GIVENS

Address:	5/4 S. CLAYTOW ST. BLOOMINGTON, IL.
Present Owner:	IRENE JOHNSON
Parcel Number:	21-04-484-006
Historical Name:	
Construction Date:	C/RCA 1900
Photo:	Roll No. 13 Frame No. 22
Architect/ Builder:	
Materials:	WOOD FRAME & TRIM, ALUMINUM SIDING, BRICK FOUNDATION & CHIMNEY
Overall shape or pl	an, number of stories and roof shape:
Subsidiary Building	s: <u>GARAGE</u>
Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction: SIDING APPUFD
Potential National	Register:
a. Individually	(yes/no)
b. As a part of a	district (yes/no) (ye
	wilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) istorical associations.
)	
Surveyor:	11-5-90

Address:	515 S. CLAYTONST. BLOOMINGTON, IL.
Present Owner:	VIOLA LOWN
Parcel Number:	21-04-483-025
Historical Name:	
Construction Date:	<u>CIRCA 1900</u>
Photo:	Roll No. 13 Frame No. 20
Architect/ Builder:	
Materials:	WOOD FRAME, CLAPBOARDS ÉTRIM, BRICK FOUNDATION É CHIMNEY
Overall shape or p	lan, number of stories and roof shape: 2 570KY, HIPPED ROOF 4 SQUARE
Subsidiary Buildin	
Condition: (See d	lefinition on reverse)
	Excellent; Good; Deteriorated
Describe major phy	vsical changes from original construction: FORCH ENCLOSED.
Potential Nationa	1 Register:
a. Individually	(yes/no) (yes/no)
b. As a part of a	a district nale for potential designation - specify criteria A, B, C, D, or combination of any.
Comments: Is the and/or	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) historical associations.
Surveyor:	WILLIAM GIVENS 11-5-90

Address:	601 S. CLAYTON BLOOMINGTON, IL.
Present Owner:	BERTUS FASKING
Parcel Number:	21-09-226-014
Historical Name:	
Construction Date:	CIRCA 1900
Photo:	Roll No. <u>13</u> Frame No. <u>30</u>
Architect/ Builder:	
Materials:	ABOD FRAME & TRIM, BLOCK FOUNDATION, ALUMINUM SIDING, BRICK
	FOUNDATION
verall shape or p	AFTSMAN WITH HIPPED CENTRAL BLOCK & OFF-CENTER
SHAPED CR	AFTEMAN WITH HIPPED CENTRAL BLOCK & OFF-CENTER
Subsidiary Building	is:
Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	Excellent; Good/; Deteriorated sical changes from original construction:
Describe major phys	Excellent; Good; Deteriorated
Describe major phy	Excellent; Good _v; Deteriorated Sical changes from original construction:
Describe major phy USE & A Potential National	Excellent; Good; Deteriorated Sical changes from original construction:
Describe major phy USE & A Potential National a. Individually b. As a part of a	Excellent; Good; Deteriorated Sical changes from original construction:
Describe major phy USE & A Potential National a. Individually b. As a part of a	Excellent; Good; Deteriorated Sical changes from original construction:
Describe major phy USE & A Potential National a. Individually b. As a part of a	Excellent; Good; Deteriorated Sical changes from original construction:
Potential National a. Individually b. As a part of a c. Explain ration	Excellent; Good; Deteriorated Sical changes from original construction:
Potential National a. Individually b. As a part of a c. Explain ration	Excellent; Good; Deteriorated sical changes from original construction:
Potential National a. Individually b. As a part of a c. Explain ration	Excellent; Good; Deteriorated sical changes from original construction:

Address:	602 S. CLAYTON BLOOMINGTON, IL.		
Present Owner:	DOUGLAS WARLOW		W W W W W W W W W W W W W W W W W W W
Parcel Number:	21-09-227-001		
Historical Name:			
Construction Date:	C/RCA 1900	•	
Photo:	Roll No. 13 Frame No. 29		
Architect/ Builder:			
Materials:	WOOD FRAME, CLAPBOLL & TRIM, BRICK FOOKE	RATION & CHIMNEY	
	an, number of stories and roof shape:	2 /2 STORY HI CABLE & FULL WIDTH	PED ROOF PORCH
Subsidiary Building	· · · · · · · · · · · · · · · · · · ·		
Condition: (See de	finition on reverse) Excellent ; Good	; Deteriorated	
Describe major phys	ical changes from original construction	•	
Potential National	Register:		
a. Individually b. As a part of a		(yes/no)/ (yes/no) criteria A, B, C, D, or combinati	
and/or h	uilding common, special or unique (one istorical associations.	-of-a-kind) in any regard and spec	ify feature(s)
Surveyor:	11-5-90		

DEFINITIONS FOR CONDITION:

EXCELLENT - All original architectural details are apparently intact and major elements (foundations, walls, windows and roof) are in repair.

GOOD - Almost all of the elements characterizing "EXCELLENT" but missing some original details and requiring some work but not stabilization.

DETERIORATED - All or some major elements (foundations, walls, windows and roof) require replacement. Original architectural details may or may not still be present.

CRITERIA FOR EVALUATION OF NATIONAL REGISTER POTENTIAL:

The quality of significance in American history, architecture, archeology, engineering and culture is present in districts, sites, buildings, structures and objects that possess integrity of location, setting, design, materials, workmanship, feeling and association:

- A. that are associated with events that have made a significant contribution to the broad patterns of our history; or
- B. that are associated with the lives of persons significant in our past; or
- C. that embody the distinctive characteristics of a type, period or method of construction, or that represent the work of a master, or that possess high artistic values, or that represent a significant and distinguishable entity whose components may lack individual distinction; or
- D. that have yielded, or may be likely to yield, information important in prehistory or history.

Address:	302 N. CLINION BLOOMINGTON, IL.	· :	
Present Owner:	MARGARETHIGGINS		
Parcel Number:	21-04-427-005		nyn
Historical Name:	DOWAR RENTA CAR		
Construction Date:	CIRCA 1975		
Photo:	Roll No Frame No24	The same of the sa	
Architect/ Builder:			
Materials:	CONCRETE FLOOR, WOOD FRAME, PLYWOOD:	SIDING , SHAKE SHING	OLE BOOF
) Overall shape or p	plan, number of stories and roof shape:	1 STORY, FLAT-	-TOPPED, HIPPE
Subsidiary Buildin			
Condition: (See	definition on reverse)	/	
	Excellent; Good	; Deteriorated	
Describe major phy	ysical changes from original construction	:	
Potential Nationa	1 Register:		
a. Individually		(yes/no) (yes/no) criteria A, B, C, D, or combina	NO ation of any.
Comments: Is the and/or	building common, special or unique (one- historical associations.	of-a-kind) in any regard and sp	pecify feature(s)
			•
Surveyor:Date:	WILLIAM GIVENS		

Address:	BLOOMINGTON, IL.
Present Owner:	PERRYOSNOWITS
Parcel Number:	21-04-437-001
Historical Name:	
Construction Date:	<u>ARCA 1900</u>
Photo:	Roll No. 13 Frame No. 32
Architect/ Builder:	
Materials:	WOOD FRAME & TRIM, ALVMINUM SIDING, PARGETED FOUNDATION,
overall shape or pl	BRICK PIEKS Lan, number of stories and roof shape: 2 /2 570RY, CROSSED GABLED
Subsidiary Building	gs:
Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction: <u>SIDING APPCIED</u>
Potential National	Register:
a. Individually	(yes/no) //
b. As a part of ac. Explain rationa	district (yes/no) // & ale for potential designation - specify criteria A, B, C, D, or combination of any.
	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) nistorical associations.
Surveyor:Date:	WILLIAM GIVENS

Address:	204 S. CLINTON BLOOMINGTON, IL.
Present Owner:	JANA WOOD
Parcel Number:	21-04-441-002
Historical Name:	
Construction Date:	
Photo:	Roll No. <u>13</u> Frame No. <u>34</u>
Architect/ Builder:	
Materials:	NOOD FRAME & TRIM, ARTIFICIAL SIDING, BRICK FOUNDATION
) Overall shape or pl	an, number of stories and roof shape: RECTANGULAR SHAPED, 1/2
Subsidiary Building	
Condition: (See de	finition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction: ARTIFICIAL SIDING APPLIED
Potential National	Register:
a. Individually	(yes/no) (yes/no) (yes/no)
b. As a part of a c. Explain rationa	ale for potential designation - specify criteria A, B, C, D, or combination of any.
	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) distorical associations.
Surveyor: ///	ULIAM 6/UENS 11-5-90

)			
Address:	406 S. CLINTON BLOOMINGTON, IL		
Present Owner:	BETHEL CHURCH		
Parcel Number:	21-04-482-007		
Historical Name:	BETHEL CHURCH		
Construction Date	e: CIRCA 1945		
Photo:	Roll No. <u>14</u> Frame No. <u>3</u>		
Architect/ Builder:	<u> </u>		
Materials:	BRICK WALLS, WOOD TRIM & ASPHA	LT SHINGLE ROOF	
overall shape or CARLE Subsidiary Build	OOFED CHURCH STRUC	_KREGULAR SHAPED , I STORY TURE WITH L-SHAPED FLAT ROOFED	
Condition: (See	definition on reverse)		
	Excellent; Good	Deteriorated	
Describe major pl	hysical changes from original construction	on: _FLAT ROOFED ADDITION	
Potential Nation	al Register:		
a. Individually		(yes/no)	
b. As a part ofc. Explain ratio	a district onale for potential designation - specify	(yes/no) <u>NO</u> criteria A, B, C, D, or combination of any.	
·			
	e building common, special or unique (one r historical associations.	e-of-a-kind) in any regard and specify feature(s)	
Survoyor!	WILLIAM GIVERIS		

Address:	501 S. CLINTON BLOOMINGTON,IL.		
Present Owner:	DOROTHY FINGER		
Parcel Number:	21-04-484-008		
Historical Name:			
Construction Date:	CIRCA 1890		
Photo:	Roll No. 14 Frame No. 4	La la	
Architect/ Builder:		The second secon	
Materials:	WOOD FRAME & TRIN ASPHALT COMPOSITION PIERS & CHIMNEY	1, SIDING, BRICK FOUNDATION,	
verall shape or pl	verall shape or plan, number of stories and roof shape: RECTANGULAR SHAPED, 1578RY GABLE FRONT FAMILY		
Subsidiary Building			
Condition: (See de	efinition on reverse)		
	Excellent; Good	; Deteriorated	
Describe major physical changes from original construction: 5/D/NG APPLIED, FRONT			
Potential National	Register:		
a. Individually		(yes/no) $\sqrt{\mathcal{E}}$	
b. As a part of a c. Explain rationa		(yes/no) (yes/no) criteria A, B, C, D, or combination of any.	
	ouilding common, special or unique (one- istorical associations.	-of-a-kind) in any regard and specify feature(s)	
)			
Surveyor: //	11LIAM GIVENS	•	

,	•	
Address:	502 S. CLINTON BLOOMINGTON, IL	
Present Owner:	ROGER EHLERS	
Parcel Number:	21-04-482-009	
Historical Name:		
Construction Date:	CIRCA 1899-1900	
Photo:	Roll No. 14 Frame No. 6	
Architect/ Builder:		
Materials:	WOOD FRAME & TRIM, ARTIFICIAL SIDING, BRIC,	K FOUNDATION & CHIMNEY
overall shape or pl WING WIT Subsidiary Building	TH LOWER ISTORY GABLES	STORY GABLE FRONT-AND-
Condition: (See de	efinition on reverse)	
	Excellent; Good;	Deteriorated
Describe major phys	sical changes from original construction:	SIDING APPLIED, FRONT
Potential National	Register:	
a. Individuallyb. As a part of ac. Explain rational	district ale for potential designation - specify criteria	(yes/no) // O (yes/no) // O a A, B, C, D, or combination of any.
	building common, special or unique (one-of-a-kin ristorical associations,	nd) in any regard and specify feature(s)
Surveyor:	WILLIAM 6/VEX5	

Address:	503 S. CLINTON BLOOMINGTON, IL.	
Present Owner:	JEFFDENNISTON	
Parcel Number:	21-04-484-009	
Historical Name:		
Construction Date:	CIRCA 1890-1900	
Photo:	CIRCA 1890-1900 Roll No. 14 Frame No. 5	
Architect/ Builder:	A CONTROL OF THE PARTY OF THE P	
Materials:	WOOD FRAME & TRIM, ARTIFICIAL SIDING, BRICK FOUNDATION, CHIMNEY & PERCH PIERS	
verall shape or pl	an, number of stories and roof shape: <u>TESHAPED</u> / STORY GABIE	
Subsidiary Building		
Condition: (See de:	finition on reverse)	
	Excellent; Good; Deteriorated	
Describe major phys.	ical changes from original construction: PORCH ADDED AFTER 1900, SIDING REPLACED OR COVERED	
Potential National N	Register:	
a. Individually b. As a part of a c c. Explain rational	district (yes/no) (ye	
Comments: Is the building common, special or unique (one-of-a-kind) in any regard and specify feature(s) and/or historical associations.		
Surveyor: //	11L/AM 6/VENS 11-6-90	

Address:	505 S. CLINTON BLOOMINGTON, IL
Present Owner:	RITA GADDY
Parcel Number:	21-04-484-010
Historical Name:	
Construction Date:	CIRCA 1890-1900
Photo:	Roll No. 14 Frame No. 7
Architect/ Builder:	
Materials:	WOOD FRAME & TRIM, ARTIFICIAL SIDING, BRICK FOUNDATION & CHIMNEY, BRICK VENEER (FRONT PORCH), CONCRETE STEPS
orall share or pl	an, number of stories and roof shape: RECTANGULAR SHAPED, 1/2
S700V	GABLE FRONT WITHENCLOSED FULL WIDTH PORCH
	s: <u>GARAGE</u>
Condition: (See de	finition on reverse)
	Excellent ; Good ; Deteriorated
Describe major phys	ical changes from original construction: PORCH ENCLOSED, BRICK
VENEER A	APPLIED ARTIFICIAL SIDING APPLIED
Potential National	Register:
a. Individually	(yes/no) = 100 $(yes/no) = 100$ $(yes/no) = 100$
b. As a part of ac. Explain rationa	the for potential designation - specify criteria A, B, C, D, or combination of any.
	•
	wilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) istorical associations.
,	
Surveyor:	WILLIAM GIVENS

Address:	507 S. CLINTON BLOOMINGTON, IL	SON CONTROL	oran e de la companya
Present Owner:	H. TUTTLE		
Parcel Number:	21-04-484-011		
Historical Name:			
Construction Date:	CIRCA 1890-1900		
Photo:	Roll No. 14 Frame No. 8		
Architect/ Builder:			
Materials:	WOOD FRAME, CLAPBOI & TRIM, BRICK FOUND,	ARDS PATION É CHIMNEY	(
Overall shape or plan, number of stories and roof shape: RECTANGULAR SHAPED 1/2 STORY GABLE FRONT FAMILY			
Subsidiary Building		<i>""</i>	
Condition: (See de	finition on reverse)		
	Excellent; Good	; Deteriorated	
Describe major phys	ical changes from original construction		TRADE
NOT OR			
<u> </u>			
Potential National	Register:	(- (-)	1/0
a. Individuallyb. As a part of a	district	(yes/no) (yes/no)	YES
b. As a part of ac. Explain rationa	le for potential designation - specify		ion of any.
	<u> </u>		
	uilding common, special or unique (one- istorical associations.	-of-a-kind) in any regard and sp∈	cify feature(s)
Surveyor: ///	LIAM GUENE		

Address:	509 S. CLINTON BLOOM INGTON, IL.	·
	•	
Present Owner:	THOMAS O'ROURKE	
Parcel Number:	21-04-484-012	
Historical Name:		
Construction Date:	C/RCA 1890-1900	
Photo:	Roll No. 14 Frame No. 9	
Architect/ Builder:		
Materials:	WOOD FRAME, CLAPSON & TRIM, SOME FISH SCI	RPS UE SIDING, BRICK FOUNDATION
) Overall shape or pl	an, number of stories and roof shape:	PECTANGULAR SHAPED, 1/2
570RY, 6	ABLE FRONT FAMILY NA	THE FULL WIDTH GABLED PORCH
Subsidiary Bnilding	•	
Condition: (See de	finition on reverse)	
	Excellent; Good	_; Deteriorated
Describe major phys	ical changes from original construction	CRAFTSMAN STYLE FRONT
DIPCH PRO	FABLY ADDED AFTER	1900,
100,91,70		
Potential National	Register:	//-
a. Individually		(yes/no)
b. As a part of ac. Explain rationa	district le for potential designation - specify	criteria A, B, C, D, or combination of any.
., <u>H</u> q.	<i>A</i>	
	wilding common, special or unique (one- istorical associations.	of-a-kind) in any regard and specify feature(s)
)		
÷		
Surveyor: //	MUIAM GIVENS	

Address: Present Owner: Parcel Number: Historical Name: Construction Date: Photo: Architect/ Builder:	511 S. CLINTON BLOOMINGTON, IL. STANLEYSMITH D1-04-484-013 CIRCA 1890-1900 Roll No. 14 Frame No. 10	
Materials:	WOOD FRAME, & TRIM, ARTIFICIAL SIDING, BRICK FOUNDATION	
Subsidiary Buildings: Stock CABLE FRONT FAMILY		
Condition: (See de	finition on reverse)	
	Excellent; Good; Deteriorated	
	ical changes from original construction:	
FKONT	PORCH ENCLOSED	
Potential National	Register:	
a. Individually	(yes/no) // (yes/no) // (yes/no)	
b. As a part of a c. Explain rationa	le for potential designation - specify criteria A, B, C, D, or combination of any.	
	uilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) astorical associations.	
Surveyor: //	11-7-90	

Address:	513 S. CLINTON
	BLOOMINGTON, IL
Present Owner:	WAVE OIL CO.
Parcel Number:	21-04-484-014 Wall
Historical Name:	
Construction Date:	CIRCA 1960
Photo:	Roll No. 14 Frame No. //
Architect/	
Builder:	
Materials:	BRICK, CHES, METAL TRIM
	1410T/Cog
) Overall shape or pl	an, number of stories and roof shape: / STOPY . \$30/APF SHAPEL
FLATTOF	an, number of stories and roof shape: / STORY, SOUARE SHAPET
Subsidiary Building	
Condition: (See de	finition on reverse)
	Excellent ; Good ; Deteriorated
Describe major phys	ical changes from original construction: XOOF DESIGN NOT
escrite major phys	A/
Potential National	Register:
a. Individually	(yes/no)
b. As a part of a	district (yes/no)
	te for potential designation specify criteria A, B, O, B, Or combination of any.
Comments: Is the b	uilding common, special or unique (one-of-a-kind) in any regard and specify feature(s)
	istorical associations.
)	
Surveyor:	WILLAM GIVENS
our veyor/	I WILLIAM

	·	
Address:	601 S. CLINTON BLOOMINGTON, IL.	
Present Owner:	HERBERT HANNER	
Parcel Number:	21-09-227-017	
Historical Name:		
Construction Date:	CIRCA 1890-1908	
Photo:	Roll No. 14 Frame No. 12	
Architect/ Builder:		
Materials:	WOOD FRAME, CLAPBOARDS & TRIM, SOME FISH SCALE SIDING, BRICK FOUNDATION & CHIMNEY	
) Overall shape or pl	an, number of stories and roof shape:	
STERY GA	ABLE FRONT FAMILY	
Subsidiary Building		
Condition: (See de	finition on reverse)	
·	Excellent Good ; Deteriorated	
Describe major physical changes from original construction:		
Potential National	Register:	
a. Individually	(yes/nó)	
b. As a part of a	district (yes/no) //ES le for potential designation - specify criteria A, B, C, D, or combination of any.	
c. Explain rationa	C	
	<i>S</i> -	
Comments: Is the building common, special or unique (one-of-a-kind) in any regard and specify feature(s) and/or historical associations.		
Surveyor:	11-1-90	

Address:	GODS. CLINTON	
	BLOOMINGTON, IL.	
Present Owner:	OLYMPIC FEDERAL	
Parcel Number:	J1-09-378-001	
Historical Name:		
Construction Date:	CIRCA 1905-1930	
Photo:	Roll No. 14 Frame No. 13	
Architect/ Builder:		
Materials:	WOOD FRAME & TRIM, ARTIFICIAL SIDING, BRICK FOUNDATION & CHIMNEY	
Overall shape or plan, number of stories and roof shape: SOUAKE SHAPED, 2/2 STORY HIPPED ROOF WITH HIPPED DORNERS		
Subsidiary Building		
Condition: (See de	finition on reverse)	
	Excellent; Good; Deteriorated	
Describe major phys	ical changes from original construction: COVER-ALC SIMIG JAS	
peserine major phys	i i i i i i i i i i i i i i i i i i i	
Potential National	Register:	
a. Individually b. As a part of a district c. Explain rationale for potential designation - specify criteria A, B, C, D, or combination of any.		
Comments: Is the building common, special or unique (one-of-a-kind) in any regard and specify feature(s) and/or historical associations.		
Surveyor:Date:	WILLIAM GUENS	

DEFINITIONS FOR CONDITION:

EXCELLENT - All original architectural details are apparently intact and major elements (foundations, walls, windows and roof) are in repair.

GOOD - Almost all of the elements characterizing "EXCELLENT" but missing some original details and requiring some work but not stabilization.

DETERIORATED - All or some major elements (foundations, walls, windows and roof) require replacement. Original architectural details may or may not still be present.

CRITERIA FOR EVALUATION OF NATIONAL REGISTER POTENTIAL:

The quality of significance in American history, architecture, archeology, engineering and culture is present in districts, sites, buildings, structures and objects that possess integrity of location, setting, design, materials, workmanship, feeling and association:

- A. that are associated with events that have made a significant contribution to the broad patterns of our history; or
- B. that are associated with the lives of persons significant in our past; or
- C. that embody the distinctive characteristics of a type, period or method of construction, or that represent the work of a master, or that possess high artistic values, or that represent a significant and distinguishable entity whose components may lack individual distinction; or
- D. that have yielded, or may be likely to yield, information important in prehistory or history.

	·	
Address:	103 N. ROBINSON BLOOMINGTON, IL.	
Present Owner:	SHIRK PRODUCTS	
Parcel Number:	21-04-438-002	
Historical Name:		
Construction Date	e: <u>CIRCA 1968</u>	
Photo:	Roll No. 14 Frame No. 15¢1	6
Architect/ Builder:		
Materials:	BRICK GLASS, CONCRETE & 57	EEC
overall shape or	plan, number of stories and roof shape	* RECTANGULAR SHAPED, 1570R,
FIATROC	FED CFFICE & WARE	HOUSE BUILDING
Subsidiary Build		
Condition: (See	definition on reverse)	
	Excellent; Good _	; Deteriorated
Describe major pl	hysical changes from original construct	ion: LOADING DOCK & OTHER
MODIFICA	ATIONS ADDED CIRCA	1975
Potential Nation		(1/2)
a. Individuallyb. As a part of		(yes/no)
c. Explain ratio	onale for potential designation - speci	fy criteria A, B, C, D, or combination of any.
	e building common, special or unique (c r historical associations.	one-of-a-kind) in any regard and specify feature(s)

Address:	203 S. ROBINSON
	BLOOMINGTON, IL.
Present Owner:	MARY HEDRICK
Parcel Number:	21-04-441-012
Historical Name:	
Construction Date:	CIRCA 1900
Photo:	Roll No. 14 Frame No. 18
Architect/ Builder:	
Materials:	WOOD FRAME, CLAPBOARES F TRIM, CONCRETE PORCH, BRICK FOUNDATION
Overall shape or pl	Lan, number of stories and roof shape: 2 STORY SABLE FRONT
Subsidiary Building	gs:
Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction: <u>NEW WOOD SIDING AFFLIE</u> T
- FRONT F	ON OT KH WICH
Potential National	Register:
a. Individually	(yes/no)
b. As a part of a c. Explain ration	district (yes/no)
	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) mistorical associations.
Surveyor:	11LIAM 61VENS

Address:	206 S. ROBINSON BLOOMINGTON, IL.		
Present Owner:	GERALD GILBERT	· · · · · · · · · · · · · · · · · · ·	
Parcel Number:	21-04-479-009		
Historical Name:			
Construction Date:	CIRCA 1980		
Photo:	Roll No. 14 Frame No. 19		
Architect/ Builder:	· · · · · · · · · · · · · · · · · · ·		
Naterials:	WOOD FRAME, PLYW SIDING, CONCRETE	OSP E FOUNDATION	
overall shape or plan, number of stories and roof shape: RECTANGULAR SHAPED) 1 STORY GABLE FRONT OFFICE BUILDING-1			
Subsidiary Building	efinition on reverse)		
COMMITTON: (See de	Excellent V; Good	; Deteriorated :	
Describe major physical changes from original construction:			
Potential National	Register:	lla.	•
a. Individually b. As a part of a district c. Explain rationale for potential designation - specify criteria A, B, C, D, or combination of any.			
Comments: Is the building common, special or unique (one-of-a-kind) in any regard and specify feature(s) and/or historical associations.			
!			
Surveyor:	WILLIAM GWENS		

		·	
Address:	208 S. ROBINSON BLOOMINGTON, IL.	·	
Present Owner:	SERVICE AMERICA CORP		
Parcel Number:	21-04-479-010		
Historical Name:	VENDERS WAREHOUSE		
Construction Date:	CIRCA 1960		
Photo:	Roll No. 14 Frame No. 20		
Architect/ Builder:			
Materials:	CONCRETE FLOOR	N FRAME & STEEL SIDING	
verall shape or plan, number of stories and roof shape: RECTANGULAR SHAPED 1 STORY FLAT ROOFED COMMERCIAL WAREHOUSE BUILDING.			
Subsidiary Building			
Condition: (See de	efinition on reverse)		
	Excellent :; Good	Deteriorated	
Describe major phys	sical changes from original construction	:	
Potential National	Register:		
a. Individually b. As a part of a	district	(yes/no)	
	building common, special or unique (one- nistorical associations.	of-a-kind) in any regard and specify feature(s)	
Surveyor: //	VILLIAM GIVENS	,	

Address:	302 S. ROBINSON BLOOMINGTON, IL.
Present Owner:	SERVICE AMERICA
Parcel Number:	21-04-479-010
Historical Name:	SERVICE AMERICA WAREHOUSE
Construction Date:	CIRCA 1960-70
Photo:	Roll No. 14 Frame No. 22
Architect/	
Builder:	
Materials:	CONCRETE BLOCK
	WALLS & FOUNDATION, SOME STEEL SIDING
Subsidiary Building Condition: (See de	An, number of stories and roof shape: CANT
Potential National	Register:
a. Individually b. As a part of a	(yes/no) NO
	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) distorical associations.
Date:	1/-7-90

Address:	305 S. ROBINSON ST.	
D	MARIE HOCHHALTER	
Present Owner:		
Parcel Number:	21-04-478-010	
Historical Name:		
Construction Date:	CIRCA 1900-1920	
Photo:	Roll No. 14 Frame No. 23	
Architect/ Builder:		
Materials:	WOOD FRAME & TRIM,	dia de la maio de material de la contraction de
	BRICK CHIMNEY & FOUN	IDATION, FOLL ASPHALT RS POOFF EXTERIOR WALL,
)		
overall snape or pr	GABLE FRONT BUILDIN	GTANGULAR SHAPED, 1/2
Subsidiary Building		
Condition: (See de	efinition on reverse)	
,	Excellent Good ;	Deteriorated .
Describe major phys	sical changes from original construction:	
Potential National	Register:	•
a. Individually		(yes/no)
b. As a part of a	ı district Male for potential designation – specify criter:	(yes/no) WES
c. Explain rationa	are for potential designation - specify criter.	id 71, b, c, b, c. combination of any
	7	
	building common, special or unique (one-of-a-k historical associations.	ind) in any regard and specify feature(s)
)	•	
	were thus cut the	
Surveyor:	WILLIAM OIVEN	

Address:	312 S. ROBINSON	
	BLOOMINGTON, IL.	
Present Owner:	MICHAELLAESCH	
Parcel Number:	21-04-479-005	
Historical Name:		
Construction Date:	OIRCA 1900-1920	
Photo:	Roll No. 14 Frame No. 24	
Architect/ Builder:		
Materials:	MOOD FRAME & SOME TRIM, PARGETED FOUNDATION, STUCCO PORCH,	
	TRIM, PARGETED FOUNDATION, STUCCO PORCH,	
) werall shape or pl	ALVM/N/W SID/NG Lan, number of stories and roof shape: 2 STORY GABLE FRONT	
FAMIL	XY	
Subsidiary Building	gs:	
Condition: (See de	efinition on reverse)	
	Excellent; Good; Deteriorated	
Describe major phys	sical changes from original construction:COVFR-ALL_SIDW6VDB	
Potential National	v/a	
a. Individually		
b. As a part of a district (yes/no) (ye		
Comments: Is the building common, special or unique (one-of-a-kind) in any regard and specify feature(s) and/or historical associations.		
)		
	1111.1001 GUEIK	
Surveyor:// Date:	11-7-90	

Address:	HODS, ROBINSON BLOOMINGTON, IL.	
Present Owner:	DONALD PETRI	
Parcel Number:	21-04-486-001	
Historical Name:		
Construction Date:	CIRCA 1900	
Photo:	Roll No. 14 Frame No. 25	
Architect/ Builder:		
Materials:	WOOD FRAME ÉTRIM, ARTIFICIAL SIDING, BRICK CHIMNEY É FOUNDATION	
overall shape or plan, number of stories and roof shape: 1575RY GABLE FRONT-		
Subsidiary Building	gs:	
Condition: (See de	efinition on reverse)	
Excellent; Good; Deteriorated		
Describe major phys	sical changes from original construction: COVER-ALL 5/P/NG	
UOB.	· .	
Potential National	Register: (yes/no) NO	
a. Individuallyb. As a part of a	district (yes/no) //O	
c. Explain rationale for potential designation - specify criteria A, B, C, D, or combination of any.		
	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) distorical associations.	
Surveyor:	ULLIAM GIVENS	

Address:	404 S. ROBINSON BLOOMINGTON, IL.	
Present Owner:	FRED WASHINGTON	
Parcel Number:	21-04-486-002	
Historical Name:		
Construction Date:	CIRCA 1900-1920	
Photo:	Roll No. 14 Frame No. 26	
Architect/ Builder:		
Materials:	WOOD FRAME & TRIM, ABBESTOS SIDING, ROCK FACED BLOCK FOUNDATION	
	lan, number of stories and roof shape: /5TORY SABLE FRONT	
FANGLY Subsidiary Building	gs:	
	efinition on reverse)	
COMMITTION: (See at	Excellent; Good; Deteriorated	
Describer and on other	sical changes from original construction:	
	FORCH ENCLOSED	
Potential National	Register:	
a. Individually	(yes/no)(yes/no)	
b. As a part of a district (yes/no)		
	building common, special or unique (one-of-a-kind) in any regard and specify feature(s) distorical associations.	
Surveyor:	WILLIAM GIVENS	

,		
Address:	405 S. ROBINSON BLOOMINGTON, IL.	
Present Owner:	STEVE JACOBSON	
Parcel Number:	21-04-482-013	
Historical Name:		
Construction Date:	CIRCA 1900-1930	
Photo:	Roll No. 14 Frame No. 27	
Architect/ Builder:	<u> </u>	
Materials:	NOOD FRAME & TRIM, ACTIFICIAL SIDING FOUNDATION	BRICK CHIMNEY PIERSE
overall shape or pl		ISTORY GABLE FRONT
Subsidiary Building		
Condition: (See de	finition on reverse)	•
	Excellent; Good	
Describe major phys	ical changes from original construction	n: SIDING APPLIED
		-
Potential National	Register:	, , , , MA
a. Individuallyb. As a part of a	district	(yes/no)
		criteria A, B, C, D, or combination of any.
	uilding common, special or unique (one Astorical associations.	-of-a-kind) in any regard and specify feature(s)
,		
Surveyor:	NILLIAM GIVENS	

Address:	406 S. ROBINSON BLOOMINGTON, 1L.	
Present Owner:		
Parcel Number:	21-04-486-002	
Historical Name:		
Construction Date:	CIRCA 1900-1920	
Photo:	Roll No. 14 Frame No. 27	
Architect/ Builder:		
Materials:	WOOD FRAME & SOME TRIM, ARTIFICIAL SIDING, BRICK FOUNDATION	
	an, number of stories and roof shape: //2 STORY GABLE	
Subsidiary Building	<i>'</i>	
Condition: (See de	finition on reverse)	
	Excellent; Good; Deteriorated	
Describe major phys	ical changes from original construction: FRONT PORCH ENCLOSED,	
SIDING	APPLIED, SHED ROOFED DORMER ADDED	
Potential National	. /.	
a. Individuallyb. As a part of a	district (yes/no) //O	
c. Explain rationale for potential designation - specify criteria A, B, C, D, or combination of any.		
, , , , , , , , , , , , , , , , , , , 		
	uilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) istorical associations.	
<i>i</i> .		
	1111 Inua CII/41/5	
Surveyor:	1/1/1/4M 6/0END 1/-7-90	

Address:	407 S. ROBINSON BLODMINGTON, IL.	
Present Owner:	EDWARD KLETZ	
Parcel Number:	21-04-482-014	
Historical Name:		
Construction Date:	CIRCA 1900-1920	
Photo:	Roll No. 14 Frame No. 28	
\rchitect/ unlder:		
Materials:	NEOD FRAME CLAPBOARDS # TRIM, BRICK FOUNDATION, PIERS & CHIMNEY,	
	SOME PLYKOOD SIDING ON PORCH	
) overall shape or pl	an, number of stories and roof shape: //2 STORY GABLE FRONT	
FAMILY	WITH LOWER GABLED FULL WIDTH PORCH	
Subsidiary Building		
Condition: (See de	finition on reverse)	
)	Excellent; Good; Deteriorated	
Describe major physical changes from original construction: FRONT PORCH ENCLOSED		
Potential National	Register:	
a. Individually	(yes/no) // // // // // // // // // // // // //	
b. As a part of ac. Explain rationa	le for potential designation - specify criteria A, B, C, D, or combination of any.	
	<u>C</u>	
	uilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) istorical associations. COULD BE CONTRIBUTING IF PORCH ALTERATIONS WERE REVERSED.	
Surveyor:Date:	WILLIAM 51UENS	

Address:	409 S. ROBINSON		
	BLOOMINGTON, IL.		
Present Owner:	HARRIET FEGER		
Parcel Number:	21-04-482-015		
Historical Name:			
Construction Date:	CIRCA 1900-1920		
Photo:	Roll No. 14 Frame No. 30		
chitect/ ilder:			
Materials:	WOOD FRAME & SOME TRIM, BRICK FOUNDATION & CHIMNEY, ALUMINUM SIDING.		
,	SOME TRIM, BRICK FOUNTATION & CHIMNEY		
	ALUMINUM SIDING.		
) overall shape or pl	an, number of stories and roof shape: 11 STORY 64BLE		
FRONT	FAMILY WITH LOWER FULL WIDTH FORCH		
	Subsidiary Buildings:		
Condition: (See de	efinition on reverse)		
	Excellent; Good; Deteriorated		
)			
	Sical changes from original construction: PORCH FNCLOSED, -ALL SIDING JOB		
COVER	-MU SIVINO SON		
Potential National	Register: (yes/no)		
a. Individuallyb. As a part of a	district (yes/no) NO		
c. Explain rationa	ale for potential designation - specify criteria A, B, C, D, or combination of any.		
	<u> </u>		
	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s)		
	<u> </u>		
Surveyor:	WILLAM GIVENS		
Date:	11-8-90		

Address:	411 S. ROBINSON BLOOMINGTON, IL.		
Present Owner:	JOHN LINK, JR.		
Parcel Number:	21-04-482-016		
Historical Name:			
Construction Date:	CIRCA 1990-1940		
Photo:	Roll No. 14 Frame No. 31	The state of the s	
Architect/ Builder:	·	25 N	
Materials:	WOOD FRAME, ALUMIN SIDING, SOME PLYM	NUM DOD SIDING, CONCRETE BLOCK PETE PORCH	
FOUNDATION, CONCRETE FORCH Verall shape or plan, number of stories and roof shape: /STORY, SIDE GABLED, RECTANGULAR SHAPED			
Subsidiary Building	, •		
Condition: (See de	finition on reverse)		
Excellent; Good; Deteriorated			
	ical changes from original construction	n: SIDING APPLIED, FRONT	
Potential National	Register:		
a. Individuallyb. As a part of ac. Explain rationa		(yes/no) //O (yes/no) //O criteria A, B, C, D, or combination of any.	
	wilding common, special or unique (one istorical associations.	-of-a-kind) in any regard and specify feature(s)	
Surveyor:Date:	WILLIAM GUENS		

Address:	4/3 S. ROBINSON BLOOMINGTON, IL	
Present Owner:	ANGIE HOUK	
Parcel Number:	21-04-482-017	
Historical Name:		
Construction Date:	CIRCA 1920	
Photo:	Roll No. 14 Frame No. 32	
Architect/ Builder:		
Materials:	WOOD FRAME & TRI	M BRICK FOUNDATION & PIERS
Subsidiary Buildin	OW MITH SHEV ROOFED IN	SIDE GABLED 1/2 STORY WHITE & EXTENDED SECONDARY FULL WIDTH PORCH
	Excellent; Good	; Deteriorated
Describe major phy	rsical changes from original constructio	n: PORCH ENCLOSED, COVER-ALL
Potential National		(yes/no)
b. As a part of a c. Explain ration	a district male for potential designation - specify	criteria A, B, C, D, or combination of any.
Comments: Is the and/or	building common, special or unique (one historical associations.	e-of-a-kind) in any regard and specify feature(s)
0	WINCIAM GIVENS	

)	
Address:	416 S. ROBINSON BLOOMINGTON, IL.
Present Owner:	SCHWULST BLDGCTR.
Parcel Number:	21-04-486-009
Historical Name:	21-04-486-009 SCHWULST-GERLING LUMBER & COAL CO.
Construction Date:	CIRICA 1922
Photo:	Roll No. 14 Frame No. 33 & 34
Architect/ Builder:	
Materials:	WOOD, STEEL &
RECTANCOLA Subsidiary Building Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phys ALTERE AS THE U	Sical changes from original construction: ALL BUILDINGS HAVE BEEN DERON THEIR ORIGINAL APPEARANCE OVER THUE SE OF THE PROPERTY HAS CHANGED OR EVOLVED
Potential National	
a. Individuallyb. As a part of ac. Explain rations	district (yes/no) (ye
	ouilding common, special or unique (one-of-a-kind) in any regard and specify feature(s) distorical associations.
Surveyor: //	11-8-90

Address:	501 S. ROBINSON BLOOMINGTON, IL.		מ יי איי
Present Owner:	JOHN STALEY		
Parcel Number:	21-04-485-008		
Historical Name:		TE SE	
Construction Date:	OIRCA 1900-1930		
Photo:	Roll No		
Architect/ Builder:			
Materials:	NOOD FRAME & TRIM, ALUMINUMSIDING ON STUCCO ON FRONT	CENTRAL BLOCK C	OF HOUSE
verall shape or pl CKAFTSMA Subsidiary Building	an, number of stories and roof shape:	SQUARE SHAPEL	, 2 STORY
Condition: (See de	finition on reverse)		
	Excellent; GoodV	; Deteriorated .	
Describe major phys	ical changes from original constructio		DING NB
Potential National	Register:		
a. Individually b. As a part of a c. Explain rationa	district de for potential designation – specify	(yes/no) (yes/no) criteria A, B, C, D, or combina	NO tion of any.
	uilding common, special or unique (one istorical associations.	-of-a-kind) in any regard and sp	ecify feature(s)
Surveyor: W	VILLIAM GOVENS		

Address:	503 S. ROBINSON
	BLOOMINGTON, IL.
Present Owner:	ETHELARNOLD
Parcel Number:	21-04-485-009
Historical Name:	
Construction Date:	CIRCA 1900-1920
Photo:	Roll No. 14 Frame No. 36
Architect/ Builder:	
Materials:	NOOD FRAME, SIDING
	NOOD FRAME, SIDING FIRM, BRICK FOUNDATION & CHIMNEY, PORCH PIERS & PORTION OF CHIMNEY STONE VENEER
)	
	Lan, number of stories and roof shape: RECTANGULAR SHAPED
	GABLE FRONT CRAFTSMAN
Subsidiary Bullding	ss: GARAGE
Condition: (See de	efinition on reverse)
	Excellent; Good; Deteriorated
Describe major phys	sical changes from original construction: PORCH ALTERED & FNCCOSED
Potential National	Register:
a. Individually	(yes/no)
b. As a part of a	district (yes/no) (yes/no) (yes/no) (le for potential designation - specify criteria A, B, C, D, or combination of any.
c. Explain rationa	specify criteria A, b, o, b, or combination or any.
Comments: Is the b	uilding common, special or unique (one-of-a-kind) in any regard and specify feature(s)
	istorical associations.
J	
Surveyor:	1111 1ANN (SV)=NS

DEFINITIONS FOR CONDITION:

EXCELLENT - All original architectural details are apparently intact and major elements (foundations, walls, windows and roof) are in repair.

GOOD - Almost all of the elements characterizing "EXCELLENT" but missing some original details and requiring some work but not stabilization.

DETERIORATED - All or some major elements (foundations, walls, windows and roof) require replacement. Original architectural details may or may not still be present.

CRITERIA FOR EVALUATION OF NATIONAL REGISTER POTENTIAL:

The quality of significance in American history, architecture, archeology, engineering and culture is present in districts, sites, buildings, structures and objects that possess integrity of location, setting, design, materials, workmanship, feeling and association:

- A. that are associated with events that have made a significant contribution to the broad patterns of our history; or
- B. that are associated with the lives of persons significant in our past; or
- C. that embody the distinctive characteristics of a type, period or method of construction, or that represent the work of a master, or that possess high artistic values, or that represent a significant and distinguishable entity whose components may lack individual distinction; or
- D. that have yielded, or may be likely to yield, information important in prehistory or history.